



US00D471612S

(12) **United States Design Patent**
Chandler

(10) **Patent No.:** **US D471,612 S**

(45) **Date of Patent:** **** Mar. 11, 2003**

(54) **GOLF CLUB TURF REPAIR DEVICE**

2001/0029213 A1 10/2001 Hendren 473/408

(76) Inventor: **Kenneth R. Chandler**, P.O. Box 26,
Catoosa, OK (US) 74015

* cited by examiner

(**) Term: **14 Years**

Primary Examiner—Mitchell Siegel

(74) *Attorney, Agent, or Firm*—Head, Johnson & Kachigian

(21) Appl. No.: **29/163,477**

(57) **CLAIM**

(22) Filed: **Jun. 28, 2002**

The ornamental design for a golf club turf repair device, as shown and described.

(51) **LOC (7) Cl.** **21-02**

DESCRIPTION

(52) **U.S. Cl.** **D21/793**

(58) **Field of Search** D21/789, 793,
D21/794; 473/286, 406, 408; D8/1

FIG. 1 is a front view of a golf club turf repair device as constructed in accordance with the present invention with the rear view being a mirror image thereof;

FIG. 2 is a side view with the opposite side being a mirror image thereof;

(56) **References Cited**

U.S. PATENT DOCUMENTS

3,763,515	A	*	10/1973	Voss	473/408
D292,059	S	*	9/1987	Heitfield	D8/1
D300,760	S	*	4/1989	Krokus	D21/793
D361,355	S	*	8/1995	Hummer	D21/793
D390,903	S	*	2/1998	Fleming	D21/793
D399,597	S	*	10/1998	Craven	D21/789
D401,379	S	*	11/1998	Goldoftas	D21/793
D410,269	S	*	5/1999	Byrd	D21/793
D439,626	S	*	3/2001	Lindsey	D21/793
6,217,465	B1		4/2001	Kenia, Jr.	473/408

FIG. 3 is a bottom end view thereof;

FIG. 4 is a top end view thereof;

FIG. 5 is a fragmentary perspective view taken generally from the top end thereof; and,

FIG. 6 is a fragmentary perspective view taken generally from the bottom end thereof.

The shaft is shown broken away in FIGS. 5 and 6 for ease of illustration.

1 Claim, 1 Drawing Sheet




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

