



US00D489522S

(12) **United States Design Patent**
Benini

(10) **Patent No.:** **US D489,522 S**

(45) **Date of Patent:** **** May 11, 2004**

(54) **SHOE UPPER**

(75) **Inventor:** **Bryon Benini**, Cardiff By The Sea, CA (US)

(73) **Assignee:** **Dye Precision, Inc.**, San Diego, CA (US)

(**) **Term:** **14 Years**

(21) **Appl. No.:** **29/167,661**

(22) **Filed:** **Sep. 18, 2002**

(51) **LOC (7) Cl.** **02-99**

(52) **U.S. Cl.** **D2/969**

(58) **Field of Search** D2/896, 902, 907, D2/943, 944, 946, 969; 36/45, 50.1, 77 M, 77 R, 83, 88, 113, 114, 126-130

(56) **References Cited**

U.S. PATENT DOCUMENTS

| | | | | | |
|------------|---|---------|-------------------|-------|--------|
| D158,953 S | * | 6/1950 | Gillis | | D2/943 |
| D309,055 S | * | 7/1990 | Whatley | | D2/969 |
| D433,560 S | * | 11/2000 | Pawlus | | D2/969 |
| D452,067 S | * | 12/2001 | Matis et al. | | D2/969 |
| D452,366 S | * | 12/2001 | Wilson | | D2/969 |
| D473,700 S | * | 4/2003 | Adrelinnas et al. | | D2/969 |

* cited by examiner

Primary Examiner—Dominic Simone

(74) *Attorney, Agent, or Firm*—Richard D. Clarke

(57) **CLAIM**

The ornamental design for a shoe upper, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a shoe upper showing my new design;

FIG. 2 is a left side (inside) view of the shoe upper;

FIG. 3 is a right side (outside) view of the shoe upper;

FIG. 4 is a top plan view of the shoe upper;

FIG. 5 is a front view of the shoe upper;



FIG. 6 is a rear view of the shoe upper; and,

FIG. 7 is a perspective view of an alternate embodiment of the shoe upper.

It should be understood that the sole of the shoe forms no part of the design of the upper. The sole is drawn in broken lines to indicate the environment with which the present shoe upper design is associated.

The dashed lines in a panel of the shoe upper, FIGS. 1-5 and 7, which panel is adjacent the side, are elements of the claimed design, said dashed lines are not intended to be taken for the broken-line rendering of the sole. In FIG. 6, the dashed lines in a panel of the shoe upper are elements of the claimed design, not to be taken for the broken-line rendering of the sole.

1 Claim, 4 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7