



US00D610931S

(12) **United States Design Patent**  
**Lyons**

(10) **Patent No.:** **US D610,931 S**  
(45) **Date of Patent:** **\*\* Mar. 2, 2010**

(54) **WARNING LIGHT WITH FLANGE**

(75) Inventor: **Jon H. Lyons**, Haddam, CT (US)

(73) Assignee: **Whelen Engineering Company, Inc.**,  
Chester, CT (US)

(\*\*) Term: **14 Years**

(21) Appl. No.: **29/315,397**

(22) Filed: **Jun. 22, 2009**

**Related U.S. Application Data**

(62) Division of application No. 29/308,561, filed on Jun. 23, 2008, now Pat. No. Des. 600,584.

(51) **LOC (9) Cl.** ..... **10-05**

(52) **U.S. Cl.** ..... **D10/114**

(58) **Field of Classification Search** ..... D10/109,  
D10/111, 113, 114; D26/28-31, 60; 362/359-368,  
362/475-478, 485-487

See application file for complete search history.

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

2,067,698	A *	1/1937	Hall	.....	404/16
D118,717	S *	1/1940	Alm	.....	D26/120
3,093,320	A *	6/1963	Knapp	.....	362/227
D205,957	S *	10/1966	Nagel	.....	D26/28
D215,117	S *	9/1969	Stahl	.....	D26/28
D221,106	S *	7/1971	Tixier	.....	D26/28
4,020,047	A *	4/1977	Burland	.....	362/235
D246,131	S *	10/1977	Schifrin	.....	D26/28
D402,576	S *	12/1998	Yang et al.	.....	D10/111
D416,342	S *	11/1999	Hussaini	.....	D26/29
D483,511	S *	12/2003	Lay et al.	.....	D26/80

D530,437	S *	10/2006	Neufeglise et al.	.....	D26/28
D542,948	S *	5/2007	Columbro	.....	D26/28
D561,360	S *	2/2008	Wang	.....	D26/28
D564,108	S *	3/2008	Lassen et al.	.....	D26/28
D584,180	S *	1/2009	Pokorny	.....	D10/111
D586,024	S *	2/2009	Wang	.....	D26/28
D589,836	S *	4/2009	Pokorny	.....	D10/114
2005/0190553	A1 *	9/2005	Lynch et al.	.....	362/227

\* cited by examiner

*Primary Examiner*—Caron Veynar

*Assistant Examiner*—George D Kirschbaum

(74) *Attorney, Agent, or Firm*—Alix, Yale & Ristas, LLP

(57) **CLAIM**

The ornamental design for the warning light and flange, as shown and described.

**DESCRIPTION**

FIG. 1 is a front perspective view of a warning light in combination with one embodiment of a flange showing my new design;

FIG. 2 is a front view of the warning light and flange of FIG. 1;

FIG. 3 is a rear view, partially illustrated in broken lines, of the warning light and flange of FIG. 1;



FIG. 4 is a top plan view of the warning light and flange of FIG. 1;

FIG. 5 is a bottom plan view of the warning light and flange of FIG. 1; and,

FIG. 6 is a left side view of the warning light assembly, the opposite right side view being a mirror image thereof.

No claim is made to the portions shown in broken lines.

**1 Claim, 6 Drawing Sheets**






Figure 1




Figure 2




Figure 3




Figure 4





Figure 5



**Figure 6**