



US00D616476S

(12) **United States Design Patent**  
**Romanyszyn et al.**

(10) **Patent No.:** **US D616,476 S**

(45) **Date of Patent:** **\*\* May 25, 2010**

(54) **BAGGER OUTER PANELS**

(76) Inventors: **Michael T. Romanyszyn**, 3720 Running Springs, San Antonio, TX (US) 78261; **Thomas J. Chadwell**, 2406 Old Well Dr., San Antonio, TX (US) 78259; **John Vira**, 326 Hackberry St., Lockhart, TX (US) 78644

(\*\*) Term: **14 Years**

(21) Appl. No.: **29/348,075**

(22) Filed: **Nov. 24, 2009**

(51) **LOC (9) Cl.** ..... **15-99**

(52) **U.S. Cl.** ..... **D15/145**

(58) **Field of Classification Search** ..... D6/432-448;  
D15/122, 145; D18/50; 53/64, 131.4, 203,  
53/266 R, 285, 459, 510, 571; 141/82, 83,  
141/114

See application file for complete search history.

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

3,364,651	A *	1/1968	Stohlquist	.....	53/284.5
D232,122	S *	7/1974	Katz	.....	D15/145
D264,723	S *	6/1982	Tsujimoto	.....	D15/145
D266,329	S *	9/1982	Tsujimoto	.....	D15/145
D266,520	S *	10/1982	Engel	.....	D15/122
D298,887	S *	12/1988	Irace	.....	D6/329
D301,890	S *	6/1989	Silbersky	.....	D15/145
D334,852	S *	4/1993	Beirise	.....	D6/436
5,630,310	A *	5/1997	Chadwell	.....	53/502
D383,526	S *	9/1997	Spaine	.....	D23/358

D403,534	S *	1/1999	Gregory et al.	.....	D6/470
D432,816	S *	10/2000	Hellwig et al.	.....	D6/441
D477,474	S *	7/2003	Milligan	.....	D6/446
6,932,124	B2 *	8/2005	Dalton et al.	.....	141/82
D522,773	S *	6/2006	Becker	.....	D6/470
D545,854	S *	7/2007	Sato et al.	.....	D15/145
D558,483	S *	1/2008	Bertch et al.	.....	D6/445
D562,369	S *	2/2008	Okamoto et al.	.....	D15/145
7,328,540	B1 *	2/2008	Rochon	.....	53/64
D605,424	S *	12/2009	Lovegrove	.....	D6/445
2005/0155330	A1 *	7/2005	Veselovsky et al.	.....	53/459

\* cited by examiner

*Primary Examiner*—Sandra Snapp

*Assistant Examiner*—Patricia Palasik

(74) *Attorney, Agent, or Firm*—John Vira

(57) **CLAIM**

The ornamental designs for a bagger outer panels, as shown and described.

**DESCRIPTION**

FIG. 1 is a front perspective view of the bagger outer panels.

FIG. 2 is a right view thereof.

FIG. 3 is a rear view thereof.


FIG. 4 is a left view thereof.

FIG. 5 is a front view thereof; and,

FIG. 6 is a top view thereof.

The broken lines in the drawings depict unclaimed environmental subject matter.

**1 Claim, 6 Drawing Sheets**






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6