



US00D621967S

(12) **United States Design Patent**  
**King**

(10) **Patent No.:** **US D621,967 S**

(45) **Date of Patent:** **\*\* Aug. 17, 2010**

(54) **SIMULATED STONE CORNER TRIM PIECE**

(75) Inventor: **Daniel W. King**, Copley, OH (US)

(73) Assignee: **Tapco International Corporation**,  
Wixom, MI (US)

(\*\*) Term: **14 Years**

(21) Appl. No.: **29/346,554**

(22) Filed: **Nov. 2, 2009**

(51) **LOC (9) Cl.** ..... **25-01**

(52) **U.S. Cl.** ..... **D25/151; D25/141**

(58) **Field of Classification Search** ..... D25/138-164,  
D25/58, 112-114; 156/71, 211; 52/275-276,  
52/311.1, 311.2, 314, 390, 506.05, 515; 428/904.4  
See application file for complete search history.

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

2,246,660	A *	6/1941	Bawtenheimer	.....	156/211
2,305,280	A *	12/1942	Strunk et al.	.....	52/314
2,331,796	A *	10/1943	Odell	.....	52/515
D153,581	S *	5/1949	Bordeaux	.....	D25/151
D153,582	S *	5/1949	Bordeaux	.....	D25/151
D163,688	S *	6/1951	Gach	.....	D25/151
5,363,623	A	11/1994	King		
5,465,486	A	11/1995	King		
5,806,185	A	9/1998	King		
2007/0082180	A1	4/2007	King		

**OTHER PUBLICATIONS**

Nailite Installation Guildelines; www.nailite.com; prior to Aug. 20, 2009.

BellaStone by Crane, Product Guide; www.ExteriorPortfolio.com/BellaStone; prior to Aug. 20, 2009.

\* cited by examiner

*Primary Examiner*—Catherine R Oliver

(74) *Attorney, Agent, or Firm*—Howard & Howard Attorneys PLLC

(57) **CLAIM**

I claim an ornamental design for a simulated stone corner trim piece, as shown and described.

**DESCRIPTION**

FIG. 1 is a broken exterior top perspective view of a simulated stone corner trim piece for covering the corner of a structure;

FIG. 2 is a broken exterior elevation view of the simulated stone corner trim piece of FIG. 1;

FIG. 3 is a broken rear elevation view of the simulated stone corner trim piece of FIG. 1, and the interior of the simulated mortar joints of FIG. 2;

FIG. 4 is a broken exterior right side elevation view of the simulated stone corner trim piece of FIG. 1;

FIG. 5 is a broken left side elevation view of the simulated stone corner trim piece of FIG. 1, and the interior of the simulated mortar joints of FIG. 4;


FIG. 6 is a broken interior top perspective view of the simulated stone corner trim piece of FIG. 1, and the interior of the simulated mortar joints of FIG. 1.


FIG. 7 is a top view of the simulated stone corner trim piece of FIG. 1; and,

FIG. 8 is a bottom view of the simulated stone corner trim piece of FIG. 1.

The break lines are shown to indicate indeterminate length. In addition, the broken lines are shown for environment only and form no part of the claimed design.

**1 Claim, 4 Drawing Sheets**





**FIG - 1**






FIG - 2




FIG - 3




FIG - 4







FIG - 5



**FIG - 6**



**FIG - 7**



**FIG - 8**