



US00D670637S

(12) **United States Design Patent**
Henson

(10) **Patent No.:** **US D670,637 S**
(45) **Date of Patent:** **** Nov. 13, 2012**

(54) **WINDSHIELD SCRUBBER**

(76) Inventor: **Marcus Durant Henson**, Bethpage, TN
(US)

(**) Term: **14 Years**

(21) Appl. No.: **29/374,532**

(22) Filed: **Aug. 29, 2011**

(51) **LOC (9) Cl.** **12-06**

(52) **U.S. Cl.** **D12/220**

(58) **Field of Classification Search** D12/219–220;
15/246, 247, 250.001, 250.4, 250.361, 250.19,
15/250.48, 250.03, 250.31–250.33, 250.351,
15/250.38, 250.201, 250.451, 250.458, 250.04,
15/250.07, 250.44

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D298,929	S	*	12/1988	Johnson et al.	D12/404
D345,329	S	*	3/1994	Kanellis et al.	D12/220
5,392,488	A	*	2/1995	Li	15/250.41
D356,287	S	*	3/1995	Kinder	D12/220
D406,094	S	*	2/1999	Lai	D12/220
D537,769	S	*	3/2007	Duvall, Jr.	D12/219
D612,715	S	*	3/2010	Weinberg et al.	D8/394

* cited by examiner

Primary Examiner — Katrina A Betton

(74) *Attorney, Agent, or Firm* — David D. Winters

(57) **CLAIM**

The ornamental design for “windshield scrubber,” as shown and described.

DESCRIPTION

FIG. 1 is a partial right side view of the windshield scrubber. The broken lines depict wiper support, wiper blade body, and cleaning pad sheath as environmental structure not claimed.

FIG. 2 is the completion of the partial right side view of the windshield scrubber seen in FIG. 1. The broken lines depict wiper support, wiper blade body, and cleaning pad sheath as environmental structure not claimed.

FIG. 3 is a partial left side view of the windshield scrubber. The broken lines depict wiper support, wiper blade body, and cleaning pad sheath as environmental structure not claimed.

FIG. 4 is the completion of the partial left side view of the windshield scrubber seen in FIG. 3. The broken lines depict wiper support, wiper blade body, and cleaning pad sheath as environmental structure not claimed.

FIG. 5 is a partial top view of the windshield scrubber. The broken lines depict wiper blade body and cleaning pad sheath as environmental structure not claimed.

FIG. 6 is the completion of the partial top view of the windshield scrubber seen in FIG. 5. The broken lines depict wiper blade body, and cleaning pad sheath as environmental structure not claimed.

FIG. 7 is a front view of the windshield scrubber. The broken lines depict wiper blade body, and cleaning pad sheath as environmental structure not claimed.


FIG. 8 is a rear view of the windshield scrubber. The broken lines depict wiper blade body, and cleaning pad sheath as environmental structure not claimed.

FIG. 9 is a partial bottom view of the windshield scrubber with area for enlargement indicated by circle. The broken lines depict wiper blade body, and cleaning pad sheath as environmental structure not claimed.

FIG. 10 is the enlargement of area indicated in FIG. 9. The broken lines depict wiper blade body, and cleaning pad sheath as environmental structure not claimed; and,

FIG. 11 is the completion of the partial bottom view of the windshield scrubber shown in FIG. 9. The broken lines depict wiper blade body, and cleaning pad sheath as environmental structure not claimed.

1 Claim, 4 Drawing Sheets






Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6



Fig. 7



Fig. 8




Fig. 9




Fig. 10




Fig. 11