

US00D701817S

(12) United States Design Patent

Takahashi et al.

(10) Patent No.:

US D701,817 S

(45) **Date of Patent:**

** Apr. 1, 2014

(54) SOUND ABSORBING PORTIONS OF PASSENGER CARRYING CAR

(71) Applicants: Central Japan Railway Company, Aichi (JP); Nippon Sharyo, Ltd., Aichi (JP)

(72) Inventors: Yukio Takahashi, Nagoya (JP); Yuya Futamura, Nagoya (JP); Koichi Hayashi, Nagoya (JP); Hiroki Tanaka, Nagoya (JP); Naoya Ozawa, Nagoya (JP); Naoyuki Maruyama, Nagoya (JP)

(73) Assignees: Central Japan Railway Company, Nagoya (JP); Nippon Sharyo Co. Ltd.,

(**) Term: 14 Years

(21) Appl. No.: 29/455,464

(22) Filed: May 21, 2013

(30) Foreign Application Priority Data

Nagoya (JP)

Nο	v 21 2012	(IP)	 2012-028593
	•	` ′	
(51)	LOC (10) C	I.	 12-06
(52)	U.S. Cl.		
	USPC	• • • • • • • • • • • • • • • • • • • •	 D12/221

USPC D12/221; D9/431–433, 44, 422, 423;

229/126, 154, 103.2, 240, 127, 157

See application file for complete search history.

Field of Classification Search

U.S. PATENT DOCUMENTS

References Cited

D415,854 S	*	10/1999	Marcus	. D28/18
			Vitoorapakorn	
			Atkin	
D419,951 S	*	2/2000	Emery et al	D12/221
			Tucker	

^{*} cited by examiner

(58)

(56)

Primary Examiner — Katrina A Betton (74) Attorney, Agent, or Firm — Oliff PLC

(57) CLAIM

The ornamental design for sound absorbing portions of passenger carrying car, as shown and described.

DESCRIPTION

FIG. 1 is a front view of sound absorbing portions of passenger carrying car;

FIG. 2 is a top view thereof;

FIG. 3 is a right-side view thereof;

FIG. 4 is a left-side view thereof;

FIG. **5** is a bottom view thereof;

FIG. 6 is a partially enlarged view thereof taken from the broken line box 6 in FIG. 3;

FIG. 7 is a partially enlarged view thereof taken from the broken line box 7 in FIG. 4;

FIG. 8 is a partially enlarged view thereof taken from the broken line box 8 in FIG. 4;

FIG. 9 is a front view of a second embodiment of the sound absorbing portions of passenger carrying car shown in FIG. 1, the second embodiment including a surface pattern:

FIG. 10 is a top view thereof;

FIG. 11 is a right-side view thereof;

FIG. 12 is a left-side view thereof;

FIG. 13 is a bottom view thereof;

FIG. 14 is a partially enlarged view thereof taken from the broken line box 14 in FIG. 11;

FIG. 15 is a partially enlarged view thereof taken from the broken line box 15 in FIG. 12;


FIG. 16 is a partially enlarged view thereof taken from the broken line box 16 in FIG. 12; and,


FIG. 17 is a partially enlarged front view of the pattern thereof defined by the areas 17' and 17" in FIG. 9.


The dot-chain lines depict a boundary between claimed and unclaimed surfaces and form no part of the claimed design.

The broken lines depict environmental subject matter only and form no part of the claimed design.

1 Claim, 6 Drawing Sheets












FIG. 6









FIG. 9



Apr. 1, 2014




FIG. 14




FIG. 16




FIG. 17