



US00D753524S

(12) **United States Design Patent**
Beldon

(10) **Patent No.:** **US D753,524 S**
(45) **Date of Patent:** **** Apr. 12, 2016**

- (54) **ROOF MONITORING DEVICE**
- (71) Applicant: **Beldon Technologies, Inc.**, San Antonio, TX (US)
- (72) Inventor: **Bradford Beldon**, San Antonio, TX (US)
- (73) Assignee: **BELDON TECHNOLOGIES, INC.**, San Antonio, TX (US)
- (**) Term: **14 Years**
- (21) Appl. No.: **29/485,721**
- (22) Filed: **Mar. 21, 2014**
- (51) **LOC (10) Cl.** **10-05**
- (52) **U.S. Cl.**
USPC **D10/106.1**
- (58) **Field of Classification Search**
USPC D13/180; D10/18, 21, 24, 25, 27, 28, D10/46, 93, 104.1, 106.5, 106.6, 113, 114, D10/116.1, 116.2, 121; D17/99
CPC B60Q 1/04; B60Q 1/26; F21S 8/026; F21S 8/04; F21V 29/004; F21V 21/02; F21V 21/04; F21V 29/2212; F21Y 2101/02; G08B 17/10
See application file for complete search history.

- D427,229 S * 6/2000 Ellis D17/22
- D435,800 S * 1/2001 Higashi et al. D10/106.5
- D436,051 S * 1/2001 Ward D10/106.2
- D439,538 S * 3/2001 Lynch D10/106.2
- D446,741 S * 8/2001 Johnson et al. D10/106.5
- D450,008 S * 11/2001 Sakurai et al. D10/106.5
- D453,484 S * 2/2002 Christianson D10/104.1
- D465,510 S * 11/2002 Edwards et al. D17/22
- D476,177 S * 6/2003 Hennessey D6/708

(Continued)

OTHER PUBLICATIONS

Smoke detector, image post date Nov. 2011, site visited Jun. 29, 2015, (online), <http://www.tripadvisor.com/LocationPhotoDirectLink-g186332-d489138-i36571263-Grand_Metropole_Hotel-Blackpool_Lancashire_England.html>.*

(Continued)

Primary Examiner — Kevin Rudzinski
Assistant Examiner — Sean D Lough
(74) *Attorney, Agent, or Firm* — Perkins Coie LLP


(57) **CLAIM**
The ornamental design for the roof monitoring device, as shown and described.

DESCRIPTION

FIG. 1 is a bottom perspective view showing the roof monitoring device;
FIG. 2 is a top perspective view showing the roof monitoring device;
FIG. 3 is a bottom view showing the roof monitoring device;
FIG. 4 is a top view showing the roof monitoring device;
FIG. 5 is a front view showing the roof monitoring device;
FIG. 6 is a back view showing the roof monitoring device;
FIG. 7 is a left side view showing the roof monitoring device; and,
FIG. 8 is a right side view showing the roof monitoring device.

1 Claim, 4 Drawing Sheets

- (56) **References Cited**
U.S. PATENT DOCUMENTS
- 4,124,958 A * 11/1978 Chiche 312/140
- D275,111 S * 8/1984 Chapman D17/20
- D301,893 S * 6/1989 Hargrove D17/22
- D317,793 S * 6/1991 Takahashi et al. D21/405
- D322,623 S * 12/1991 Craviotto et al. D17/22
- D358,352 S * 5/1995 Behlke D10/106.5
- D360,374 S * 7/1995 Tice et al. D10/106.5
- D391,512 S * 3/1998 Ch D10/106.1
- D422,523 S * 4/2000 Weid D10/113.1
- D423,389 S * 4/2000 Boyd D10/104.2
- D423,972 S * 5/2000 Hampf et al. D10/106.1



(56)

References Cited

U.S. PATENT DOCUMENTS

D494,235 S * 8/2004 Edwards D21/710
 D501,165 S * 1/2005 Grove D12/188
 D519,050 S * 4/2006 Lee D10/113.1
 D520,394 S * 5/2006 Li et al. D10/113.1
 D561,990 S * 2/2008 Berg et al. D3/204
 D571,950 S * 6/2008 Wedding et al. D26/120
 D590,451 S * 4/2009 Gold et al. D21/473
 D601,282 S * 9/2009 Howard et al. D26/26
 D605,501 S * 12/2009 Pham et al. D9/425
 D618,383 S * 6/2010 Zhang et al. D26/120
 D622,929 S * 9/2010 Anderson D1/127
 D623,633 S * 9/2010 Bliss et al. D14/233
 D629,972 S * 12/2010 Peters et al. D29/124
 D641,276 S * 7/2011 Greppi D11/1
 D646,004 S * 9/2011 VanderSchuit D26/24
 D648,806 S * 11/2011 Wood et al. D20/99
 D651,926 S * 1/2012 Akiyama et al. D10/106.5

D652,760 S * 1/2012 Greppi D11/86
 D653,576 S * 2/2012 Thalhammer D10/106.5
 D665,289 S * 8/2012 Thalhammer D10/106.5
 D681,140 S * 4/2013 Lynch et al. D21/707
 D682,810 S * 5/2013 Chen D14/222
 D685,436 S * 7/2013 Menting D21/398
 D695,990 S * 12/2013 Pearson D1/115
 D709,781 S * 7/2014 Chung D10/105
 D726,037 S * 4/2015 Moeller D10/70
 2001/0010803 A1 * 8/2001 Freeman et al. 422/126
 2001/0038337 A1 * 11/2001 Wickstead et al. 340/628
 2013/0170205 A1 * 7/2013 Abel et al. 362/235
 2014/0260687 A1 * 9/2014 Beldon 73/862.381

OTHER PUBLICATIONS

Birdsill Holly fire hydrant in situ, image post date 1869, site visited Jun. 29, 2015, (online), <https://en.wikipedia.org/wiki/Birdsill_Holly#/media/File:1869BirdsillHollyHydrantSideTop.jpg>.*

* cited by examiner




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8