



US00D779301S

(12) **United States Design Patent** (10) **Patent No.:** **US D779,301 S**
Garavaglia et al. (45) **Date of Patent:** **** Feb. 21, 2017**

(54) **SAFETY CUTTER BODY**

(71) Applicant: **Pacific Handy Cutter, Inc.**, Irvine, CA (US)

(72) Inventors: **Joseph P. Garavaglia**, Newport Beach, CA (US); **Brandon L. Spoelstra**, Huntington Beach, CA (US); **Markus Gropl**, Huntington Beach, CA (US); **Chris Lung**, Santa Ana, CA (US)

(73) Assignee: **PACIFIC HANDY CUTTER, INC.**, Irvine, CA (US)

(**) Term: **14 Years**

(21) Appl. No.: **29/516,022**

(22) Filed: **Jan. 28, 2015**

(51) **LOC (10) Cl.** **08-03**

(52) **U.S. Cl.**
USPC **D8/99**

(58) **Field of Classification Search**
USPC D8/98, 99, 105, 107
CPC B26B 5/001; B26B 5/003; B26B 11/00;
B26B 1/08
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D420,270 S * 2/2000 Martone D8/99
6,249,975 B1 * 6/2001 Lin B26B 5/001
30/162
D458,526 S * 6/2002 Budrow D8/99
6,553,674 B1 * 4/2003 Budrow B26B 5/001
30/125
D509,419 S * 9/2005 Chung D8/99

D511,288 S * 11/2005 Brown D8/99
D524,138 S * 7/2006 Chih D8/99
D572,107 S * 7/2008 Maraia D8/99
D587,553 S * 3/2009 Constantine D8/99
D629,274 S * 12/2010 Wu D8/99
D675,898 S * 2/2013 Wu D8/99
D731,280 S * 6/2015 Dahlberg D8/99
D731,281 S * 6/2015 Dahlberg D8/99

* cited by examiner

Primary Examiner — Phillip S Hyder

(74) *Attorney, Agent, or Firm* — Henricks, Slavin & Holmes LLP

(57) **CLAIM**

The ornamental design for a safety cutter body, as shown and described.

DESCRIPTION

This application is related to U.S. patent appl. Ser. No. 14/608,171, entitled "Safety Cutter" filed herewith.

FIG. 1 is a left side front perspective view of a safety cutter body showing our new design;

FIG. 2 is a right side rear perspective view thereof;

FIG. 3 is a left side rear perspective view thereof;

FIG. 4 is a right side front perspective view thereof;

FIG. 5 is a left side view thereof;

FIG. 6 is a right side view thereof;

FIG. 7 is a top view thereof;


FIG. 8 is a bottom view thereof;

FIG. 9 is a front view thereof; and,

FIG. 10 is a rear view thereof.

The broken lines in the drawings show features of the safety cutter body that are included for illustrative purposes only and form no part of the claim.

1 Claim, 8 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10