



US00D779923S

(12) **United States Design Patent**  
**Del Rossa**

(10) **Patent No.:** **US D779,923 S**

(45) **Date of Patent:** **\*\* Feb. 28, 2017**

(54) **JIG FOR REPAIRING BROKEN MOUNTING STUDS**

(71) Applicant: **Jeffrey Del Rossa**, Pittsburgh, PA (US)

(72) Inventor: **Jeffrey Del Rossa**, Pittsburgh, PA (US)

(\*\*) Term: **15 Years**

(21) Appl. No.: **29/536,112**

(22) Filed: **Aug. 13, 2015**

(51) **LOC (10) Cl.** ..... **08-05**

(52) **U.S. Cl.**

USPC ..... **D8/354**; D8/349; D12/223

(58) **Field of Classification Search**

USPC .... D8/14, 71, 349, 354, 382, 394, 396, 398,  
D8/499; D12/223

CPC ..... F28D 9/0006; F28D 9/0025; F28F 3/025;  
F02M 26/32; F01N 13/1805; F01N  
13/1811; F01N 13/1827; F01N 13/1838;  
B23B 49/02; B23B 51/0054

See application file for complete search history.

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

- 3,396,361 A \* 8/1968 Sussman ..... H01L 23/40  
174/16.3
- 4,119,335 A \* 10/1978 Rieffle ..... F16L 21/022  
285/249
- 4,517,585 A \* 5/1985 Ridout ..... H01L 23/4006  
174/16.3
- D339,277 S \* 9/1993 Snider ..... D8/71
- D363,500 S \* 10/1995 Ichihara ..... D15/143
- D367,249 S \* 2/1996 Ott ..... D12/114
- 5,505,546 A \* 4/1996 Okude ..... F16C 35/02  
384/276
- D371,139 S \* 6/1996 Waskiewicz ..... 384/428
- 5,755,464 A \* 5/1998 Erwin ..... F01N 13/1805  
285/328
- D420,688 S \* 2/2000 Ichihara ..... D15/143

- 6,079,753 A \* 6/2000 Erwin ..... F01N 13/1805  
285/328
- 6,484,913 B1 \* 11/2002 Hancock ..... B60R 7/14  
211/64
- D695,788 S \* 12/2013 Wilkinson ..... D15/7
- D745,119 S \* 12/2015 Browning ..... D23/265
- D747,952 S \* 1/2016 Attanasio ..... D8/349

(Continued)

**OTHER PUBLICATIONS**

Promaxx, Image post date unknown, site visited on Jul. 18, 2016 (online), 1 page, <<http://www.promaxxtool.com/nino.html>>.\*

(Continued)

*Primary Examiner* — Sandra Snapp

*Assistant Examiner* — Ieisha Price

(74) *Attorney, Agent, or Firm* — Picadio Sneath Miller & Norton, P.C.; Robert L. Wagner


(57) **CLAIM**

The ornamental design for a jig for repairing broken mounting studs, as shown and described.

**DESCRIPTION**

FIG. 1 is a top perspective view of a jig for repairing broken mounting studs showing my design; FIG. 2 is a top plan view thereof; FIG. 3 is a side elevation view thereof; FIG. 4 is an opposite side elevation view thereof; FIG. 5 is a bottom plan view thereof; FIG. 6 is an end elevation view thereof; and, FIG. 7 is an opposite end elevation view thereof. The broken lines in the drawings illustrate portions of the jig for repairing broken mounting studs and form no part of the claimed design.

**1 Claim, 3 Drawing Sheets**



(56)

**References Cited**

U.S. PATENT DOCUMENTS

2002/0008387 A1\* 1/2002 Vasudeva ..... F01N 13/16  
285/405  
2008/0087409 A1\* 4/2008 Nakamura ..... F28D 9/0025  
165/165  
2011/0047997 A1\* 3/2011 Goplen ..... F01N 3/34  
60/317  
2013/0149057 A1\* 6/2013 Nisikawa ..... B23B 51/048  
408/83  
2013/0152291 A1\* 6/2013 Stonecipher ..... E03D 11/16  
4/252.1  
2016/0273440 A1\* 9/2016 Eadie ..... F01N 13/1805

OTHER PUBLICATIONS

ProMAXX Tools—Nino, Image post date Nov. 23, 2015, site visited  
on Jul. 18, 2016 (online), 1 page, <[https://www.youtube.com/  
watch?v=JaXrq59JbWo](https://www.youtube.com/watch?v=JaXrq59JbWo)>.\*

\* cited by examiner




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7