



US00D814669S

(12) **United States Design Patent** (10) **Patent No.:** **US D814,669 S**  
**Scoda** (45) **Date of Patent:** **\*\* Apr. 3, 2018**

(54) **EMERGENCY LIGHT STRAP**  
(71) Applicant: **Michael Scoda**, Morganville, NJ (US)  
(72) Inventor: **Michael Scoda**, Morganville, NJ (US)

D668,808 S \* 10/2012 Hoover ..... D26/60  
9,115,858 B2 \* 8/2015 Levante ..... F21S 4/005  
D737,714 S \* 9/2015 Lutze ..... D10/115  
D762,887 S \* 8/2016 Hawkins ..... D26/24  
D768,892 S \* 10/2016 Lockart ..... D26/25  
D777,356 S \* 1/2017 Maas ..... F21V 11/02  
D26/24

(\*\*) Term: **15 Years**

\* cited by examiner

(21) Appl. No.: **29/582,797**

*Primary Examiner* — Brian N. Vinson

(22) Filed: **Oct. 31, 2016**

(74) *Attorney, Agent, or Firm* — Dunlap Bennett & Ludwig PLLC

(51) **LOC (11) Cl.** ..... **26-01**

(52) **U.S. Cl.**  
USPC ..... **D26/25; D10/115**

(57) **CLAIM**

The ornamental design for an emergency light strap, as shown and described.

(58) **Field of Classification Search**  
USPC ..... D26/1, 24, 25, 60, 113, 118, 10, 131,  
D26/138; D10/109.1, 111, 114.1, 115,  
D10/121

**DESCRIPTION**

CPC ..... F21S 4/003; F21S 4/00; F21S 8/00; F21S  
4/005; F21V 23/002; F21V 23/00; F21V  
21/00; F21V 21/08; F21V 33/00; F21V  
33/0004; F21V 33/0024; F21V 33/0088;  
F21V 11/02; E06B 9/262; E06B 9/264;  
E06B 9/54; E04F 10/00; F21W 2121/00  
See application file for complete search history.

FIG. 1 is a front perspective view of an emergency light strap;  
FIG. 2 is a front elevation view thereof;  
FIG. 3 is a rear elevation view thereof;  
FIG. 4 is a left side elevation view thereof, the right side  
elevation view being a mirror image thereof;  
FIG. 5 is a top plan view thereof;  
FIG. 6 is a bottom plan view thereof; and,  
FIG. 7 is a perspective view of the emergency light strap  
shown in use.

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

D212,722 S \* 11/1968 Kahn ..... D10/115  
D370,740 S \* 6/1996 Rance ..... D26/138  
D455,224 S \* 4/2002 Yando ..... D26/130  
D565,750 S \* 4/2008 Egawa ..... D26/1  
D598,583 S \* 8/2009 Levine ..... D26/25  
D614,780 S \* 4/2010 Huang ..... D26/1

The broken lines showing a traffic light in FIG. 7 depicts environmental subject matter that forms no part of the claimed design, while the remaining broken lines shown in the drawings depict portions of the emergency light strap that form no part of the claimed design.

**1 Claim, 3 Drawing Sheets**




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5





FIG. 6






FIG. 7