



US00D851515S

(12) **United States Design Patent**
Zhao et al.

(10) **Patent No.:** **US D851,515 S**
(45) **Date of Patent:** **** Jun. 18, 2019**

(54) **FAULT DIAGNOSIS INSTRUMENT**

(56) **References Cited**

(71) Applicant: **AUTOPHIX TECH CO., LTD.**,
Shenzhen, Guangdong (CN)

(72) Inventors: **Yutao Zhao**, Guangdong (CN); **Qing Huang**, Guangdong (CN); **Jian Hao**, Guangdong (CN)

(73) Assignee: **AUTOPHIX TECH CO., LTD.**,
Shenzhen (CN)

(**) Term: **15 Years**

(21) Appl. No.: **29/632,619**

(22) Filed: **Jan. 9, 2018**

(51) **LOC (11) Cl.** **10-04**

(52) **U.S. Cl.**
USPC **D10/78**

(58) **Field of Classification Search**
USPC D10/78
CPC G01L 19/08; G01L 19/083; G01L 19/086;
G01L 19/10; G01L 19/12; G01L 19/14;
G01L 19/141; G01L 19/142; G01L
19/143; G01L 19/144; G01L 19/45; G01L
19/146; G01L 19/147; G01L 19/148;
G01L 19/149; G01L 19/16; G07C 5/00;
G07C 5/002; G07C 5/004; G07C 5/006;
G07C 5/008; G07C 5/02; G07C 5/04;
G07C 5/06; G07C 5/08; G07C 5/0808;
G07C 5/0816; G07C 5/0825; G07C
5/0833; G07C 5/0841; G07C 5/085;
G07C 5/0858; G07C 5/0866; G07C
5/0875; G07C 5/0883; G07C 5/0891;
G07C 5/10

U.S. PATENT DOCUMENTS

D629,318	S	*	12/2010	Disch	D10/78
7,860,619	B2	*	12/2010	Bertosa	G07C 5/0808 340/438
8,600,610	B2	*	12/2013	Bertosa	G07C 5/008 701/33.2
9,014,907	B2	*	4/2015	Lipscomb	G07C 5/008 701/115
9,275,503	B2	*	3/2016	Chen	G07C 5/0808
9,646,432	B2	*	5/2017	Madison	G07C 5/085
D806,592	S	*	1/2018	Protti	D10/78
D806,593	S	*	1/2018	Sova	D10/78

* cited by examiner

Primary Examiner — Antoine Duval Davis

(74) *Attorney, Agent, or Firm* — Hauptman Ham, LLP

(57) **CLAIM**

The ornamental design for fault diagnosis instrument, as shown and described.


DESCRIPTION

FIG. 1 is a front view thereof;
FIG. 2 is a rear view thereof;
FIG. 3 is a left side view thereof;
FIG. 4 is a right side view thereof;
FIG. 5 is a top plan view thereof;
FIG. 6 is a bottom plan view thereof
FIG. 7 is a front-bottom-right side perspective view thereof;
FIG. 8 is a front-top-right side perspective view thereof; and,
FIG. 9 is a rear-bottom-left side perspective view thereof,
with fault diagnosis instrument being in use.

The broken lines shown in the drawings represent portions of fault diagnosis instrument which form no part of the claimed design.

See application file for complete search history.

1 Claim, 9 Drawing Sheets






Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9