



US00D888631S

(12) **United States Design Patent** (10) **Patent No.:** **US D888,631 S**  
**Battams et al.** (45) **Date of Patent:** **\*\* Jun. 30, 2020**

(54) **VEHICLE SIDE SILL**  
(71) Applicant: **Jaguar Land Rover Limited**, Whitley,  
Coventry (GB)  
(72) Inventors: **Robert Battams**, Coventry (GB);  
**Massimo Frascella**, Coventry (GB)  
(73) Assignee: **Jaguar Land Rover Limited**, Whitley  
Coventry (GB)  
(\*\*) Term: **15 Years**  
(21) Appl. No.: **29/673,429**  
(22) Filed: **Dec. 14, 2018**

(30) **Foreign Application Priority Data**  
Jun. 28, 2018 (EM) ..... 005329133  
(51) **LOC (12) Cl.** ..... **12-16**  
(52) **U.S. Cl.**  
USPC ..... **D12/190**  
(58) **Field of Classification Search**  
USPC ... D12/190, 181, 192, 400, 90-92, 196-200,  
D12/172, 163, 110, 114  
CPC ..... B60S 9/205; B60R 13/005; B60R 13/02  
See application file for complete search history.

(56) **References Cited**  
U.S. PATENT DOCUMENTS  
3,659,887 A \* 5/1972 Marquette ..... B60R 13/04  
293/128  
D386,458 S \* 11/1997 Smith ..... D12/167

D484,080 S \* 12/2003 Yamamoto ..... D12/190  
D613,220 S \* 4/2010 Ikeda ..... D12/190  
D660,755 S \* 5/2012 Inoue ..... D12/190  
D807,247 S \* 1/2018 Malina ..... D12/167  
D807,890 S \* 1/2018 Roberts ..... D14/440  
D850,344 S \* 6/2019 DeMatthews ..... D12/190  
D856,435 S \* 8/2019 Wood ..... D21/561  
D867,947 S \* 11/2019 Park Cheng ..... D12/190

\* cited by examiner


*Primary Examiner* — Katrina A Betton  
(74) *Attorney, Agent, or Firm* — Wood Herron & Evans  
LLP

(57) **CLAIM**  
The ornamental design for a vehicle side sill, as shown and  
described.

**DESCRIPTION**

FIG. 1 is a front view of a vehicle side sill according to the  
present invention.  
FIG. 2 is a front right perspective view of the vehicle side  
sill shown in FIG. 1.  
FIG. 3 is a front right elevated perspective view thereof.  
FIG. 4 is a rear view thereof.  
FIG. 5 is a rear left perspective view thereof.  
FIG. 6 is a rear left elevated perspective view thereof.  
FIG. 7 is a right side view thereof.  
FIG. 8 is a left side view thereof.  
FIG. 9 is a top view thereof.  
FIG. 10 is a bottom view thereof; and,  
FIG. 11 is another front view thereof, but mounted on a  
vehicle to show environmental structure, the vehicle being  
unclaimed and shown in broken lines.

**1 Claim, 11 Drawing Sheets**






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5



FIG. 6



FIG. 7





FIG. 8




FIG. 9




FIG. 10




FIG. 11