



US00D908293S

(12) **United States Design Patent** (10) **Patent No.:** **US D908,293 S**
Roost et al. (45) **Date of Patent:** **** *Jan. 19, 2021**

(54) **CAT POST**

(71) Applicant: **Pet Fusion, LLC**, Fanwood, NJ (US)

(72) Inventors: **Andrew Roost**, Fanwood, NJ (US);
Theodore Elliott, Bentleyville, OH
(US); **Pablo Ignacio Parra Henriquez**,
Madrid (ES)

(73) Assignee: **Pet Fusion, LLC**, Fanwood, NJ (US)

(*) Notice: This patent is subject to a terminal disclaimer.

(**) Term: **15 Years**

(21) Appl. No.: **29/670,839**

(22) Filed: **Nov. 20, 2018**

(51) **LOC (13) Cl.** **30-99**

(52) **U.S. Cl.**
USPC **D30/160**

(58) **Field of Classification Search**
USPC D30/160; D6/681.3, 675.1, 349;
D11/118, 125; 119/28.5, 29, 83, 702,
119/706-711; 15/160, 206
CPC A01K 15/024; A01K 15/025
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D255,610 S * 6/1980 Clarke-Fodor 119/706
4,253,423 A * 3/1981 Kaplan A01K 15/024
119/706
D648,079 S * 11/2011 Haaf D30/160
D685,959 S * 7/2013 Paculdo D30/160
D723,752 S * 3/2015 Davis-David D30/160
D774,709 S * 12/2016 Kellogg D30/160

D801,091 S * 10/2017 Elledge D6/682
2004/0194731 A1 * 10/2004 Lineberry A01K 15/024
119/706
2011/0253060 A1 * 10/2011 Schotthoefer A01K 15/024
119/706

OTHER PUBLICATIONS

“New brancy-out cat post”, posted Nov. 10, 2018[Online], [Retrieved Nov. 27, 2019], from internet: https://www.amazon.ca/PetFusion-Branch-Out-Scratching-Innovative-Replacement/product-reviews/B07H7VF38X/ref=cm_cr_getr_d_paging_btm_next_2?ie=UTF8&reviewerType=all_reviews&sortBy=recent&pageNumber=2.*

* cited by examiner

Primary Examiner — Sandra S Snapp

Assistant Examiner — Mehri F Bajoul

(74) *Attorney, Agent, or Firm* — Myers Wolin, LLC

(57) **CLAIM**

The ornamental design for a cat post, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a cat post showing our new design;

FIG. 2 is a front elevation view thereof;

FIG. 3 is a rear elevation view thereof;

FIG. 4 is a left side elevation view thereof;


FIG. 5 is a right side elevation view thereof;

FIG. 6 is a top view thereof; and,

FIG. 7 is a bottom view thereof.

The broken lines in the drawings depict portions of the cat post that form no part of the claimed design.

1 Claim, 7 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7