

US00D934367S

(12) **United States Design Patent** (10) **Patent No.:** **US D934,367 S**
Mandeville (45) **Date of Patent:** **** Oct. 26, 2021**

(54) **DIVOT REPAIR TOOL**
(71) Applicant: **Mark Mandeville**, Fletcher, NC (US)
(72) Inventor: **Mark Mandeville**, Fletcher, NC (US)
(73) Assignee: **Microtech Knives, Inc.**, Bradford, PA (US)
(**) Term: **15 Years**
(21) Appl. No.: **29/736,628**
(22) Filed: **Jun. 2, 2020**
(51) **LOC (13) Cl.** **21-02**
(52) **U.S. Cl.**
USPC **D21/793**
(58) **Field of Classification Search**
USPC D21/789, 793, 794
CPC A63B 57/00; A63B 57/50; A63B 57/12;
A63B 57/16; A63B 57/20; A63B 57/30;
A63B 57/35
See application file for complete search history.

(56) **References Cited**
U.S. PATENT DOCUMENTS
3,360,807 A * 1/1968 Mauck A63B 57/353
7/158
D238,436 S * 1/1976 McKelvey D21/793
D285,233 S * 8/1986 Owen D21/793
D306,057 S * 2/1990 Vaughan, Jr. D21/793
5,388,824 A * 2/1995 Reimers A63B 57/00
473/406
5,405,133 A * 4/1995 Upton A63B 57/50
172/378
5,449,169 A * 9/1995 Hardin A63B 57/50
473/408
D369,637 S * 5/1996 Digerness D21/793
5,562,553 A * 10/1996 Digerness A63B 57/207
473/408
6,413,174 B1 * 7/2002 Roberts A63B 57/207
473/408

6,428,430 B1 * 8/2002 Chong A63B 57/50
473/408
6,620,062 B2 * 9/2003 Taylor A63B 57/50
473/408
D500,828 S * 1/2005 Pace D21/793
6,837,807 B1 * 1/2005 Kerr A63B 57/50
473/286
D534,982 S * 1/2007 Miller D21/793
7,238,125 B2 * 7/2007 Dymling A63B 57/207
473/408
D570,946 S * 6/2008 Oas D21/793
7,686,710 B2 * 3/2010 Leiber A63B 57/50
473/408
D651,272 S * 12/2011 Corcoran D21/793
D669,952 S * 10/2012 Zwart D21/793
8,342,986 B2 * 1/2013 Rourke A63B 57/207
473/408

(Continued)

OTHER PUBLICATIONS

www.twotalentsdesign.com website showing the product Flick'It (OTF Divot Tool).

Primary Examiner — Mitchell I. Siegel
(74) *Attorney, Agent, or Firm* — Steve LeBlanc, LLC


(57) CLAIM

The ornamental design for a divot repair tool, as shown and described.

DESCRIPTION

FIG. 1 is a front perspective view of the divot repair tool; FIG. 2 is a front view of the divot repair tool; FIG. 3 is a rear view of the divot repair tool; FIG. 4 is a top side view of the divot repair tool; FIG. 5 is a bottom side view of the divot repair tool; FIG. 6 is a left view of the divot repair tool; and, FIG. 7 is a right view of the divot repair tool. The dotted lines shown in FIGS. 1-7 are environmental only and form no part of the claimed design.

1 Claim, 5 Drawing Sheets



(56) **References Cited**

U.S. PATENT DOCUMENTS

D683,413	S	*	5/2013	Revert		D21/793
8,616,994	B2	*	12/2013	Kwon		A63B 57/207
						473/283
D699,804	S	*	2/2014	Zwart		D21/793
D700,262	S	*	2/2014	Zwart		D21/793
D700,263	S	*	2/2014	Zwart		D21/793
D704,021	S	*	5/2014	Rubin		D8/85
D736,052	S	*	8/2015	Rubin		D8/85
D737,394	S	*	8/2015	Cruz		D21/793
9,168,440	B1	*	10/2015	Dean		A63B 71/0669
D823,415	S	*	7/2018	Zwart		D21/793
D824,465	S	*	7/2018	Zwart		D21/793
2010/0022330	A1		1/2010	Rourke et al.		
2011/0081994	A1		4/2011	Rourke		

* cited by examiner




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7