

US00D963198S

(12)

United States Design Patent

Livengood et al.

(10)

Patent No.:

US D963,198 S

(45)

Date of Patent:

** Sep. 6, 2022

(54) PICTURE FRAME BALUSTER

(71) Applicants: **Derrick Livengood**, Delta Junction, AK (US); **Danielle Livengood**, Delta Junction, AK (US)

(72) Inventors: **Derrick Livengood**, Delta Junction, AK (US); **Danielle Livengood**, Delta Junction, AK (US)

(**) Term: 15 Years

(21) Appl. No.: 29/732,847

(22) Filed: Apr. 28, 2020

(51) LOC (13) Cl. 25-02

(52) U.S. Cl. USPC D25/40

(58) Field of Classification Search
USPC D25/38.1, 40, 126, 128, 130, 132
CPC . E04F 11/181; E04F 11/1817; E04F 11/1842; E04F 11/1844; E04F 11/1846
See application file for complete search history.

(56) References Cited

U.S. PATENT DOCUMENTS

3,233,377	A	2/1966	Louis	
5,056,283	A	10/1991	Sapinski	
D399,980	S *	10/1998	Masse	D25/38.1
6,374,562	B1	4/2002	Crowly	
6,775,937	B2	8/2004	Ruana	
D519,215	S *	4/2006	Walker	D25/38.1
D546,475	S *	7/2007	Walker	D25/38.1
D556,342	S *	11/2007	Walker	D25/38.1
D567,391	S *	4/2008	Walker	D25/38.1
D595,864	S *	7/2009	Dong	D25/38.1
7,594,643	B2 *	9/2009	Ross	E04F 11/1842
				256/22
D622,409	S *	8/2010	Dong	D25/38.1

D622,870	S *	8/2010	Gibbs	D25/38.1
2010/0095567	A1	4/2010	Li	
2013/0081340	A1	4/2013	Williams	

OTHER PUBLICATIONS

House of Forgings triple rectangle hollow <https://houseofforgings.net/shop/16-6-5-triple-rectangle-hollow/> Available Jan. 17, 2021 (Year: 2021).*

* cited by examiner

Primary Examiner — Leanne Was-Englehart
(74) Attorney, Agent, or Firm — Boudwin Intellectual Property; Daniel Boudwin


(57) CLAIM

The ornamental design for a picture frame baluster, as shown and described.

DESCRIPTION

FIG. 1 shows a perspective view of the picture frame baluster.
FIG. 2 shows a front end elevation view of the picture frame baluster.
FIG. 3 shows a rear end elevation view of the picture frame baluster.
FIG. 4 shows a right side elevation view of the picture frame baluster.
FIG. 5 shows a left side elevation view of the picture frame baluster.
FIG. 6 shows a top plan view of the picture frame baluster; and,
FIG. 7 shows a bottom plan view of the picture frame baluster.
The broken lines depict portions of the picture frame baluster that form no part of the claimed design.
The shade lines in the Figures show contour and not surface ornamentation.

1 Claim, 4 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7