

[54] TROUBLE LIGHT

[76] Inventor: William W. Buchanan, 914
Magdalene, Houston, Tex. 77024

[**] Term: 14 Years

[21] Appl. No.: 921,360

[22] Filed: Jul. 3, 1978

[51] Int. Cl. D26—02

[52] U.S. Cl. D26/45

[58] Field of Search D10/114; D26/28, 36,
D26/37, 38, 39, 40, 41, 45, 46, 48; 340/321, 90;
362/109, 258, 64, 61, 296

[56] References Cited

U.S. PATENT DOCUMENTS

D. 193,591	9/1962	Kitasako	D26/45
D. 245,282	8/1977	Brinkmann	D26/45
3,244,873	4/1966	Leutheuser	362/258
3,322,944	5/1967	Mellyn	362/258
3,474,244	10/1969	Hanlon	362/296


Primary Examiner—Susan J. Lucas
Attorney, Agent, or Firm—Clarence E. Eriksen

[57] CLAIM

The ornamental design for a trouble light, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a trouble light showing my new design.
FIG. 2 is a front view of the trouble light of FIG. 1 on a reduced scale.
FIG. 3 is a side view of the trouble light of FIGS. 1 and 2 on a reduced scale.
FIG. 4 is a rear view of the trouble light of FIGS. 1-3 on a reduced scale.
FIG. 5 is a top view of the trouble light of FIGS. 1-4 on a reduced scale.
FIG. 6 is a bottom view of the trouble light of FIGS. 1-5 on a reduced scale.
The broken lines in the drawings are shown for illustrative purposes only.






FIG. 1

FIG. 2





FIG. 5

FIG. 3




FIG. 4




FIG. 6

