

[54] **TEAT VALVE**

[76] **Inventors:** **Mark L. Anderson**, 100 McKay Ave., Spring Valley, Wis. 54767; **Francis W. Child**, 1307 Southfork Rd., Cody, Wyo. 82414

[**] **Term: 14 Years**

[21] **Appl. No.: 291,379**

[22] **Filed: Aug. 10, 1981**

[52] **U.S. Cl.** **D24/53; D24/54; D23/19; D24/23**

[58] **Field of Search** 137/844; 24/23, 53, 24/54; 119/14.21; D23/19, 26; 251/231

[56] **References Cited**

U.S. PATENT DOCUMENTS

| | | | |
|------------|---------|---------------------|-----------|
| 15,192 | 6/1856 | Peale . | |
| 111,932 | 2/1871 | Hewitt . | |
| D. 232,780 | 9/1974 | Zackheim | D24/23 |
| D. 262,654 | 1/1982 | Anderson | D24/54 |
| D. 268,048 | 2/1983 | Ueda | D23/19 |
| 274,447 | 3/1883 | Kennish . | |
| 876,775 | 1/1908 | Crittenden . | |
| 1,045,326 | 11/1912 | Ruffin . | |
| 1,242,314 | 10/1917 | Bean . | |
| 1,688,795 | 10/1928 | Aas . | |
| 1,797,339 | 3/1931 | Gudmand-Hoyer . | |
| 1,995,051 | 3/1935 | Benson | 31/59 |
| 2,347,988 | 5/1944 | Burke | 137/69 |
| 2,524,764 | 10/1950 | Burke | 137/69 |
| 2,572,658 | 10/1951 | Perkins | 137/844 X |
| 2,682,057 | 6/1954 | Lord | 3/1 |
| 2,687,731 | 8/1954 | Iarussi et al. | 128/349 |
| 2,704,076 | 3/1955 | Larson | 128/348 |
| 2,907,341 | 10/1959 | Boyer et al. | 137/844 X |
| 3,030,960 | 4/1962 | Turner et al. | 128/348 |

| | | | |
|-----------|---------|-----------------------|------------|
| 3,071,139 | 1/1963 | Nivholson | 128/350 |
| 3,118,468 | 1/1964 | Bochan | 137/525.1 |
| 3,122,161 | 2/1964 | Pfeifer | 137/493.2 |
| 3,195,786 | 7/1965 | Vogt | 222/394 |
| 3,308,788 | 3/1967 | Noorlander | 119/14.52 |
| 3,416,562 | 12/1968 | Freeman | 137/512.15 |
| 3,445,916 | 5/1969 | Schulte | 29/458 |
| 3,477,438 | 11/1969 | Allen et al. | 128/349 |
| 3,579,642 | 5/1971 | Heffernan et al. | 3/1 |
| 3,589,392 | 6/1971 | Meyer | 137/525.1 |
| 3,703,898 | 11/1972 | Zackheim | 128/261 |
| 3,709,220 | 1/1973 | Boyden | 128/132 |
| 3,721,229 | 3/1973 | Panzer | 128/2 A |
| 3,768,102 | 10/1973 | Kwan-Gett et al. | 3/1 |
| 3,821,956 | 7/1974 | Gordhamer | 128/343 |
| 3,825,157 | 7/1974 | Herzig | 222/212 |
| 3,861,416 | 1/1975 | Wichterle | 137/525.3 |
| 3,881,448 | 5/1975 | Hallstrom | 119/14.19 |
| 3,938,197 | 2/1976 | Milo | 3/1.5 |

OTHER PUBLICATIONS

Honda Service Repair Handbook, Clymer Publications, p. 11.


Primary Examiner—Bernard Ansher
Attorney, Agent, or Firm—Burd, Bartz & Gutenkauf

[57] **CLAIM**

The ornamental design for a teat valve, substantially as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of the teat valve showing our new design;
FIG. 2 is a side elevational view thereof;
FIG. 3 is a top plan view of FIG. 2;
FIG. 4 is a bottom plan view of FIG. 2; and
FIG. 5 is a sectional view taken along the line 5—5 of FIG. 2.






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5