


[54] GOLF BALL MARK REPAIR TOOL
[76] Inventor: Steven Tyrer, P.O. Box 824,
Southold, N.Y. 11971
[**] Term: 14 Years
[21] Appl. No.: 289,576
[22] Filed: Dec. 21, 1988
[52] U.S. Cl. D21/234
[58] Field of Search D21/234; D32/47;
273/32 B

[56] References Cited
U.S. PATENT DOCUMENTS
D. 198,037 4/1964 Thayer D21/234
D. 225,756 1/1973 Stephens D21/234
D. 254,211 2/1980 Gutknecht D21/234

Primary Examiner—Melvin B. Feifer
Assistant Examiner—P. Hyder

Attorney, Agent, or Firm—Kelly and Hulme
[57] CLAIM
The ornamental design for a golf ball mark repair tool,
as shown and described.

DESCRIPTION
FIG. 1 is a perspective view of a golf ball mark repair tool showing my new design;
FIG. 2 is a front elevation thereof;
FIG. 3 is a side elevation thereof;
FIG. 4 is a rear elevation thereof;
FIG. 5 is the opposite side elevation thereof;
FIG. 6 is a top plan view thereof;
FIG. 7 is a bottom plan view thereof;
FIG. 8 is a front elevation of an alternate embodiment of the tool of FIG. 1;
FIG. 9 is a side elevation of FIG. 8;
FIG. 10 is the opposite side elevation thereof;
FIG. 11 is a bottom plan view of FIG. 8.






FIG. 1




FIG. 6




FIG. 2



FIG. 3




FIG. 4



FIG. 5

FIG. 7




FIG. 9




FIG. 8



FIG. 10




FIG. 11