



US00D359245S

United States Patent [19]

Lee et al.

[11] Patent Number: Des. 359,245

[45] Date of Patent: ** Jun. 13, 1995

[54] PLUMB BOB ASSEMBLY

[75] Inventors: Leonard G. Lee; John S. Lynn;
Thomas S. Gardiner, all of Ottawa,
Canada

[73] Assignee: Lee Valley Tools Ltd., Ottawa,
Canada

[**] Term: 14 Years

[21] Appl. No.: 24,886

[22] Filed: Jun. 22, 1994

[52] U.S. Cl. D10/65; D10/61;
D10/62

[58] Field of Search D10/61, 62, 65; D3/215,
D3/273; D9/339; 33/369-373, 391-394;
206/305, 822

[56] References Cited

U.S. PATENT DOCUMENTS

D. 336,049 6/1993 Patridge, Jr. D10/65 X
2,135,211 1/1938 Johnson 33/393 X

FOREIGN PATENT DOCUMENTS

689069 9/1930 France 33/393
268892 1/1951 Switzerland 33/393

OTHER PUBLICATIONS

Photograph of plumb bobs from the 1994 *American Woodworker Calendar*, ©1993.

Primary Examiner—Antoine Duval Davis

Attorney, Agent, or Firm—Kilpatrick & Cody

[57] CLAIM

The ornamental design for a plumb bob assembly, as shown and described.

DESCRIPTION

FIG. 1 is an exploded perspective view of the plumb bob assembly of the present invention showing the bob exploded out of the combination container and spool; FIG. 2 is a side elevation view of the plumb bob shown in FIG. 1;

FIG. 3 is a top plan view of the plumb bob shown in FIG. 2;

FIG. 4 is a bottom plan view of the plumb bob shown in FIG. 2;

FIG. 5 is a side elevation view of the combination container and spool shown in FIG. 1;

FIG. 6 is a sectional view of the combination container and spool taken along line 6—6 in FIG. 5;


FIG. 7 is a top plan view of the combination container and spool shown in FIG. 5;

FIG. 8 is a bottom plan view of the combination container and spool shown in FIG. 5;

FIG. 9 is a side elevation view of the plumb bob assembly shown in FIG. 1; and,

FIG. 10 is a sectional view of the combination container and spool taken along line 10—10 in FIG. 9.

The solid line depiction of the combination container and spool in FIGS. 2-4 have been eliminated for ease of illustration. The solid line depiction of the plumb bob in FIGS. 5-7 have been eliminated for ease of illustration.






FIG 1




FIG 2




FIG 3




FIG 4




FIG 5




FIG 6




FIG 7




FIG 8




FIG 9




FIG 10