



US00D378547S

United States Patent [19]
Holland

[11] **Patent Number: Des. 378,547**
[45] **Date of Patent: **Mar. 25, 1997**

[54] **LEATHER SHOEHORN**

[75] Inventor: **John M. Holland**, Larkspur, Calif.

[73] Assignee: **Holland Brothers**, San Francisco, Calif.

[**] Term: **14 Years**

[21] Appl. No.: **44,290**

[22] Filed: **Sep. 21, 1995**

[52] **U.S. Cl.** **D2/642**

[58] **Field of Search** D2/641, 642, 643;
223/113, 114, 115, 116, 117, 118; D3/201,
208, 210

[56] **References Cited**

U.S. PATENT DOCUMENTS

D. 58,797	8/1921	Mayhew	D2/642
D. 160,905	11/1950	Tarrant	D2/642 X
D. 223,974	6/1972	Tsutsui	D3/210 X
D. 224,365	7/1972	Lewis	D2/642
D. 238,976	2/1976	Dolas	D3/208
D. 290,063	6/1987	Wright	D2/642
1,522,922	1/1925	Smiley	223/118
2,483,714	10/1949	Shaffer	D2/642 X
3,088,639	5/1963	Sexton	D2/642 X
3,436,000	4/1969	Batista	223/118
4,290,539	9/1981	Lowery	D2/642 X

Primary Examiner—Paula A. Mortimer
Attorney, Agent, or Firm—Cushman Darby & Cushman IP
Group of Pillsbury Madison & Sutro LLP

[57] **CLAIM**

The ornamental design for a leather shoehorn, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a leather shoehorn showing my new design; the looped member is broken away for purposes of illustration;

FIG. 2 is a top plan view thereof, the bottom plan view is a mirror image;

FIG. 3 is a side elevational view thereof, the opposite side is a mirror image;

FIG. 4 is a front elevational view of a second embodiment of a leather shoehorn showing my new design, the bottom is a mirror image, the only difference being the absence of the looped member and corresponding through-hole;


FIG. 5 is an end elevational view thereof, the view shown being from the broad end of the shoehorn of my design; and,

FIG. 6 is an end elevational view thereof, the view shown being from the narrow end of the shoehorn of my design.

The loop member in FIGS. 1, 2 and 3 is shown broken away for ease of illustration.

FIGS. 4, 5, and 6 show an alternate design wherein the loop member and the hole on the narrow end of the shoehorn are absent.

1 Claim, 1 Drawing Sheet






Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6