



US00D383516S

United States Patent [19]

Stevens

[11] Patent Number: **Des. 383,516**

[45] Date of Patent: ****Sep. 9, 1997**

[54] **GOLF BALL MARK REPAIRER DEVICE ATTACHABLE TO THE GRIP END OF A PUTTER**

4,862,970	9/1989	Hlavacek	473/408 X
4,955,609	9/1990	Kassen	473/286
5,029,854	7/1991	Laskowitz et al.	473/408 X
5,511,785	4/1996	Rusin, Jr.	473/408 X

[76] Inventor: **Robert W. Stevens**, 1706 Lehigh Cir., Sun City Center, Fla. 33570

Primary Examiner—Sandra L. Morris
Assistant Examiner—Cheri Cohen

[**] Term: **14 Years**

[57] **CLAIM**

[21] Appl. No.: **49,911**

The ornamental design for golf ball mark repairer device attachable to the grip end of a putter, as shown and described.

[22] Filed: **Feb. 2, 1996**

[51] LOC (6) Cl. **21-02**

[52] U.S. Cl. **D21/234**

[58] Field of Search D21/234, 208; D8/13; 473/406, 408, 285, 286

DESCRIPTION

FIG. 1 is a front elevational view of the golf ball mark repairer device attachable to the grip end of a putter showing my new design;

FIG. 2 is a rear elevational view thereof;

FIG. 3 is a right view thereof;

FIG. 4 is a left view thereof;

FIG. 5 is a top plan view thereof; and,

FIG. 6 is a bottom plan view thereof.

[56] **References Cited**

U.S. PATENT DOCUMENTS

D. 46,579	10/1914	Peterson	D8/13
D. 169,412	4/1953	Bodelon	D8/13 X
D. 300,760	4/1989	Krokus, Sr.	D21/234
4,799,684	1/1989	Rango	473/286

1 Claim, 3 Drawing Sheets




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

