

US00D432901S

United States Patent [19]
McDonald

[11] **Patent Number: Des. 432,901**

[45] **Date of Patent: ** Oct. 31, 2000**

[54] **BRACKET**

D. 369,957 5/1996 Blanton D9/373

[75] Inventor: **Roderick Raymond McDonald**, New South Wales, Australia

Primary Examiner—Holly Baynham
Attorney, Agent, or Firm—Birch, Stewart, Kolasch & Birch, LLP

[73] Assignee: **Unistrut Australia Pty Limited**, New South Wales, Australia

[**] Term: **14 Years**

[57] **CLAIM**

The ornamental design for a bracket, as shown.

[21] Appl. No.: **29/097,904**

DESCRIPTION

[22] Filed: **Nov. 17, 1998**

FIG. 1 is a perspective view of a bracket showing my new design;

[30] **Foreign Application Priority Data**

May 18, 1998 [AU] Australia 1433/98

FIG. 2 is a front view thereof;

[51] **LOC (7) Cl.** **08-05**

FIG. 3 is a rear view thereof;

[52] **U.S. Cl.** **D8/354**

FIG. 4 is a left side view thereof with the right side being a mirror image;

[58] **Field of Search** D8/349, 354, 363;
248/200, 300, 201

FIG. 5 is a plan view thereof; and,


FIG. 6 is an inverted plan view thereof.

[56] **References Cited**

U.S. PATENT DOCUMENTS

D. 314,326 2/1991 Sachs D8/373

1 Claim, 2 Drawing Sheets






FIG 1




FIG 2




FIG 3




FIG 4




FIG 5




FIG 6

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : Des 432,901S
DATED : October 31, 2000
INVENTOR(S) : Roderick McDonald

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page,

Item [30] **Foreign Application Priority Data**, please change the number from "1433/98" to -- 1432/98 --.

Signed and Sealed this

Eleventh Day of December, 2001

Attest:

Nicholas P. Godici

Attesting Officer

NICHOLAS P. GODICI
Acting Director of the United States Patent and Trademark Office