



US00D436152S

(12) **United States Design Patent**  
**Sanford, III**

(10) **Patent No.:** **US D436,152 S**

(45) **Date of Patent:** **\*\* Jan. 9, 2001**

(54) **GOLF BALL MARK REPAIR TOOL**

(76) Inventor: **Laurence H. Sanford, III**, 901 Cherry Valley Rd., Princeton, NJ (US) 08540

(\*\*) Term: **14 Years**

(21) Appl. No.: **29/122,362**

(22) Filed: **Apr. 26, 2000**

(51) **LOC (7) Cl.** ..... **21-02**

(52) **U.S. Cl.** ..... **D21/793**

(58) **Field of Search** ..... D21/793; 473/286, 473/408

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

- D. 190,333 5/1961 Gunderson .
- D. 197,205 12/1963 Estwing .
- D. 197,342 1/1964 Doble .
- D. 209,973 1/1968 Klitzner .
- D. 225,756 1/1973 Stephens .

- D. 272,461 1/1984 Burns .
- D. 360,450 7/1995 Louden et al. .
- 5,121,519 \* 6/1992 Haugom ..... 473/408

\* cited by examiner

*Primary Examiner*—Mitchell Siegel  
(74) *Attorney, Agent, or Firm*—Woodbridge & Associates, P.C.; Richard C. Woodbridge

(57) **CLAIM**

The ornamental design for a golf ball mark repair tool, as shown and described.

**DESCRIPTION**

FIG. 1 is a perspective view of the golf ball mark repair tool according to the preferred embodiment thereof.

FIG. 2 is a front elevational view thereof.

FIG. 3 is a right side elevational view thereof.

FIG. 4 is a rear elevational view thereof.

FIG. 5 is a top pan view thereof; and,

FIG. 6 is a bottom pan view thereof.

**1 Claim, 1 Drawing Sheet**




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

