

US00D600274S

(12) **United States Design Patent**
Schoning

(10) **Patent No.:** **US D600,274 S**
(45) **Date of Patent:** **** Sep. 15, 2009**

(54) **QUICK PROCESS SALES/TIP PERCENTAGE CALCULATOR**

(76) Inventor: **Herb O. Schoning**, 3316 State Route 59,
Ravenna, OH (US) 44266

(**) Term: **14 Years**

(21) Appl. No.: **29/320,272**

(22) Filed: **Jun. 24, 2008**

(51) **LOC (9) Cl.** **18-01**

(52) **U.S. Cl.** **D18/7**

(58) **Field of Classification Search** D14/218,
D14/341-347, 387; D18/1, 2, 4.4, 4.5, 6-12,
D18/12.1-12.3; D21/512; 235/58 R, 59 A,
235/59 BC, 59 BD, 59 BE, 59 BF, 59 BG,
235/59 BH, 59 CP, 59 T, 59 TP, 61 R; 708/100,
708/105, 130

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

4,277,837 A 7/1981 Stuckert
D262,119 S 12/1981 Cannella
4,446,528 A 5/1984 Marmon
4,458,320 A 7/1984 Sutton
D382,271 S * 8/1997 Akwiwu D14/218

6,076,079 A 6/2000 Boston et al.
D464,990 S * 10/2002 Bodum D18/7
D490,841 S * 6/2004 Castillo D18/7
D521,500 S * 5/2006 Sass D14/218
D583,812 S * 12/2008 Asibey D14/346
D584,305 S * 1/2009 Rothman D14/346
D589,081 S * 3/2009 Wages D18/7
2003/0005004 A1 1/2003 Soliman

* cited by examiner

Primary Examiner—Caron Veynar

Assistant Examiner—Garth Rademaker

(74) *Attorney, Agent, or Firm*—Kyle Fletcher

(57) **CLAIM**

The ornamental design for a quick process sales/tip percentage calculator, as shown.

DESCRIPTION

FIG. 1 is a front elevation view of a quick process sales/tip percentage calculator;


FIG. 2 is a rear elevation view thereof;

FIG. 3 is a right side elevation view thereof;

FIG. 4 is a top plan view thereof; and,

FIG. 5 is an isometric view thereof.

1 Claim, 2 Drawing Sheets






FIG. 1

INSTRUCTIONS:

1. PRESS NUMBER KEYS TO ENTER "COST".
2. PRESS THE "C" KEY IF YOU ENTER A WRONG COST.
3. PRESS THE "ENTER" KEY IF THE COST IS CORRECT.
4. PRESS NUMBER KEYS TO ENTER % OF SALE OR % OF TIP... THEN PRESS "ENTER" AND YOUR NEW "SALES PRICE" OR YOUR "TIP AMOUNT" WILL BE FIGURED AUTOMATICALLY FOR YOU.
5. PRESS "C" KEY TO CLEAR ALL... THEN ENTER NEW "ITEM OR CHECK" COST.

FIG. 2



FIG. 3



FIG. 4




FIG. 5