

US00D763673S

(12) **United States Design Patent**
Moreau et al.

(10) **Patent No.:** **US D763,673 S**
(45) **Date of Patent:** **** Aug. 16, 2016**

- (54) **BADGE CLIP ASSEMBLY**
- (71) Applicant: **Ty-Flot, Inc.**, Manchester, NH (US)
- (72) Inventors: **Darrell A. Moreau**, Manchester, NH (US); **Andre W. Moreau**, Spring Hill, FL (US)
- (73) Assignee: **Ty-Flot, Inc.**, Manchester, NH (US)
- (**) Term: **14 Years**
- (21) Appl. No.: **29/515,767**
- (22) Filed: **Jan. 27, 2015**
- (51) **LOC (10) Cl.** **08-08**
- (52) **U.S. Cl.**
USPC **D8/395**
- (58) **Field of Classification Search**
USPC D8/394–396, 349–356, 373, 400;
D24/138; D19/68, 99, 100, 65;
D20/22, 43, 99; D11/215
CPC H01R 11/11; H01R 11/281; B21C 1/28;
F16L 23/036; F16L 3/13; F16L 3/1058;
E04B 2/74; E04B 2/7442; G09F 3/08
See application file for complete search history.

D699,100 S * 2/2014 Moreau D8/394
D714,125 S * 9/2014 Seiders D8/331
2005/0151367 A1* 7/2005 Packard B42D 15/0086
281/21.1

FOREIGN PATENT DOCUMENTS

JP D1260464 * 1/2006
JP D1260465 * 1/2006

OTHER PUBLICATIONS

Other Latch Clamps | DE-STA-CO, online, website copyright 2016, <http://www.destaco.com/other-latch-clamps.html>, [site visited Jan. 28, 2016 7:37:53 PM].*

Baumgartens Sicurix Button ID Badge Straightap Clips—Walmart.com, online, customer review date Jul. 23, 2014, <http://www.walmart.com/ip/Baumgartens-BAU68010-I.D.-Strap-Clip-Adapter-Pack-of-25/> . . . , site visited Feb. 6, 2016.*

* cited by examiner

Primary Examiner — John Windmuller

Assistant Examiner — John R Yeh

(74) *Attorney, Agent, or Firm* — Mesmer & Deleault PLLC

(57) **CLAIM**

The ornamental design for a badge clip assembly, as shown and described.

(56) **References Cited**

U.S. PATENT DOCUMENTS

- 1,792,923 A * 2/1931 O'Neil A43C 11/00
24/69 SK
- 3,595,458 A * 7/1971 Prigl B21C 1/28
226/164
- 3,618,995 A * 11/1971 McLean E05C 19/14
292/113
- D261,102 S * 10/1981 Hoover 294/86.4
- D313,205 S * 12/1990 Mejias D11/215
- D333,775 S * 3/1993 Krape D8/331
- D391,895 S * 3/1998 Anscher D11/215
- D432,402 S * 10/2000 Hyp D8/383
- D454,292 S * 3/2002 Plummer D8/331
- D464,994 S * 10/2002 Rosen D19/65
- D467,973 S * 12/2002 Rosen D19/65
- D477,987 S * 8/2003 Adams D19/65
- D557,746 S * 12/2007 Hammar D20/43
- D683,653 S * 6/2013 Moreau D11/215

DESCRIPTION

FIG. 1 is a left-side and front perspective view of the badge clip assembly showing our new design in a closed position with a fastener installed in the clip;
FIG. 2 is a right-side and rear perspective view thereof;
FIG. 3 is a left-side and front perspective view of the badge clip assembly shown in an open position;
FIG. 4 is a right-side and rear perspective view thereof shown in the open position and with the fastener separated from the clip;
FIG. 5 is a left-side elevational view of the badge clip assembly shown in a closed position and with the fastener installed in the clip;
FIG. 6 is a right-side elevational view of the badge clip assembly shown in a closed position and with the fastener separated from the clip;




FIG. 7 is a right-side elevational view of the badge clip assembly shown in the open position with the fastener installed in the clip;

FIG. 8 is a left-side elevational view of the badge clip assembly shown in the open position with the fastener installed in the clip;

FIG. 9 is a front elevational view of the badge clip assembly shown in the open position with the fastener installed in the clip;

FIG. 10 is a rear elevational view of the badge clip assembly shown in the closed position with the fastener installed in the clip;

FIG. 11 is a rear elevational view of the badge clip assembly shown in the closed position with the fastener separated from the clip;

FIG. 12 is a front elevational view of the badge clip assembly shown in an open position with the fastener installed in the clip;

FIG. 13 is a front elevational view of the badge clip assembly shown in the closed position with the fastener installed in the clip;

FIG. 14 is a top plan view of the badge clip assembly shown in the closed position with the fastener separated from the clip; and,

FIG. 15 is a bottom plan view of the badge clip assembly with the fastener separated from the clip.

The broken lines illustrate portions of the badge clip assembly that form no part of the claimed design.

1 Claim, 7 Drawing Sheets

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11





Fig. 12




Fig. 13




Fig. 14




Fig. 15

