

US00D800529S

(12) **United States Design Patent**
Leibowitz

(10) **Patent No.:** **US D800,529 S**

(45) **Date of Patent:** **** Oct. 24, 2017**

(54) **DRIVE HANDLE**

(71) Applicant: **Shukla Medical**, Piscataway, NJ (US)

(72) Inventor: **Evan Leibowitz**, Linden, NJ (US)

(73) Assignee: **Shukla Medical**, Piscataway, NJ (US)

(**) Term: **15 Years**

(21) Appl. No.: **29/574,202**

(22) Filed: **Aug. 12, 2016**

(51) **LOC (10) Cl.** **08-04**

(52) **U.S. Cl.**
USPC **D8/83; D24/133**

(58) **Field of Classification Search**
USPC D8/21, 25, 82-87, 107
CPC A47J 43/26; B25B 13/463; B25B 13/468;
B25B 15/04; B25G 1/005; B25G 1/085
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D256,882 S *	9/1980	Jansson	D8/83
D307,236 S *	4/1990	Cascio	D8/82
5,437,212 A *	8/1995	Thompson	B25B 15/04
			81/63.1
5,873,288 A *	2/1999	Gauthier	B25B 13/463
			192/43.1
D421,888 S *	3/2000	Thompson	D8/83
D515,388 S *	2/2006	Howard	D8/82
D562,665 S *	2/2008	Gao	D8/83
D565,379 S *	4/2008	Williams	D8/83
D622,124 S *	8/2010	Kegg	D8/83
D655,002 S *	2/2012	Bast	D24/133

D666,725 S *	9/2012	McCormack	D24/133
D716,629 S *	11/2014	Suter	D8/82
D720,590 S *	1/2015	Carl	D8/85
D720,591 S *	1/2015	Carl	D8/85
D756,189 S *	5/2016	Liu	D8/85
2017/0100821 A1 *	4/2017	Sun	B25B 23/0035

OTHER PUBLICATIONS

Ratcheting Drivers. Downloaded Jun. 8, 2017 from <http://www.bradshaw-medical.com/products/ratchets/>.*

* cited by examiner

Primary Examiner — Philip S Hyder
Assistant Examiner — Roselynn Cody

(74) *Attorney, Agent, or Firm* — Kim Winston LLP


(57) **CLAIM**

The ornamental design for a drive handle, as shown and described.

DESCRIPTION

FIG. 1 is a front perspective view of a drive handle in accordance with the new design;
FIG. 2 is a rear perspective view of the drive handle of FIG. 1;
FIG. 3 is a top view of the drive handle of FIG. 1;
FIG. 4 is a bottom view of the drive handle of FIG. 1;
FIG. 5 is a front view of the drive handle of FIG. 1;
FIG. 6 is a rear view of the drive handle of FIG. 1;
FIG. 7 is a right side view of the drive handle of FIG. 1; and,
FIG. 8 is a left side view of the drive handle of FIG. 1.
The broken lines in the figures are directed to portions of the drive handle that form no part of the claim.

1 Claim, 5 Drawing Sheets






FIG. 1



FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7



FIG. 8