



US00D801617S

(12) **United States Design Patent** (10) **Patent No.:** **US D801,617 S**
Fox et al. (45) **Date of Patent:** **** Oct. 31, 2017**

(54) **SERVICE JACK**

(71) Applicant: **International Specialty Services, Inc.**,
Travelers Rest, SC (US)

(72) Inventors: **Robert Fox**, Greenville, SC (US);
Chad James, Greenville, SC (US)

(73) Assignee: **INTERNATIONAL SPECIALTY
SERVICES, INC.**, Travelers Rest, SC
(US)

(**) Term: **15 Years**

(21) Appl. No.: **29/571,055**

(22) Filed: **Jul. 14, 2016**

Related U.S. Application Data

(63) Continuation of application No. 29/520,241, filed on
Mar. 12, 2015, now Pat. No. Des. 764,736.

(51) **LOC (10) Cl.** **12-05**

(52) **U.S. Cl.**
USPC **D34/31**

(58) **Field of Classification Search**

USPC D34/31; 254/83, 84, 11, 93 H, 2 B, 88,
254/DIG. 3, 48, 94, 93 R, 8 B, 2 R
CPC B66F 13/00; B66F 1/00; B66F 1/02; B66F
1/06; B66F 1/08; B66F 3/30; B66F 3/25;
B66F 3/12; B66F 3/18; B66F 3/28; B66F
3/24; B66F 3/247

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D284,417 S	6/1986	Yamagishi
D296,598 S	7/1988	Hung
D332,337 S	1/1993	Wang
D480,196 S	9/2003	Hsu
D604,025 S	11/2009	Lin

D688,845 S	8/2013	Hernandez et al.
8,500,095 B1	8/2013	Salcedo
8,608,131 B2	12/2013	Kania
8,622,369 B2	1/2014	Kania
D720,514 S	12/2014	Fox et al.
D720,914 S	1/2015	Fox et al.
D720,915 S	1/2015	Fox et al.
D730,612 S	5/2015	Fox et al.
D764,736 S *	8/2016	Fox D34/31
2006/0278858 A1	12/2006	Brocchini
2008/0083913 A1	4/2008	Fang et al.

* cited by examiner

Primary Examiner — Cynthia Ramirez

(74) *Attorney, Agent, or Firm* — J. Bennett Mullinax,
LLC

(57) **CLAIM**

The ornamental design for a service jack, as shown and
described.

DESCRIPTION

FIG. 1 is a left side perspective view of a service jack
showing our new design;

FIG. 2 is a right side view of the service jack as shown in
FIG. 1;

FIG. 3 is a left side view of the service jack as shown in FIG.
1;

FIG. 4 is a rear side view of the service jack as shown in
FIG. 1;


FIG. 5 is a bottom view of the service jack as shown in FIG.
1;

FIG. 6 is a front view of the service jack as shown in FIG.
1;

FIG. 7 is a perspective view of the service jack as shown in
FIG. 1; and,

FIG. 8 is a top view of the service jack as shown in FIG. 1.
The broken lines shown in FIGS. 1-8 show portions of the
service jack only and form no part of the claimed design.

1 Claim, 8 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

