

US00D802407S

(12) **United States Design Patent** (10) **Patent No.:** **US D802,407 S**
Foerster, Jr. (45) **Date of Patent:** **** Nov. 14, 2017**

(54) **THREAD REPAIR INSERT**

(71) Applicant: **Thomas F. Foerster, Jr.**, Eagle River, WI (US)

(72) Inventor: **Thomas F. Foerster, Jr.**, Eagle River, WI (US)

(73) Assignee: **Gard Specialist Co., Inc.**, South Eagle River, WI (US)

(**) Term: **15 Years**

(21) Appl. No.: **29/545,250**

(22) Filed: **Nov. 11, 2015**

(51) **LOC (10) Cl.** **08-08**

(52) **U.S. Cl.**
USPC **D8/387; D8/397; D24/156**

(58) **Field of Classification Search**
USPC D8/382, 387, 388, 391, 393, 397, 399;
D24/156, 180, 176
CPC .. F16B 37/00; F16B 37/005; F16B 2037/007;
F16B 37/122; F16B 37/125; F16B 37/127
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

3,866,510 A * 2/1975 Eibes B21H 3/027
411/418
4,097,061 A * 6/1978 Dietlein A63C 5/06
280/607
5,547,323 A * 8/1996 Fang F16B 37/122
411/178
D411,009 S * 6/1999 Asfora D24/155
6,024,523 A * 2/2000 Oudmayer F16B 37/122
411/111
D427,684 S * 7/2000 Hansson D24/156

(Continued)

OTHER PUBLICATIONS

GARD Specialists Co. Inc: Drill Reference Chart—Large GARDSERT Sizes—p. 13, Site visited online on Jun. 14, 2017, Image post date Feb. 2017, 1 page <<http://www.gardspecialists.com/view.php?r=Gardserts.pdf&v=chptr>>.*

Primary Examiner — Sandra Snapp

Assistant Examiner — Ieisha Price

(74) *Attorney, Agent, or Firm* — Christopher A. Proskey; Brown Winick Law Firm


(57) **CLAIM**

The ornamental design for a thread repair insert, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a thread repair insert, showing the upper end of the thread repair insert;
FIG. 2 is a perspective view of a thread repair insert, showing the lower end of the thread repair insert;
FIG. 3 is an elevation view of a thread repair insert, showing the front side of the thread repair insert;
FIG. 4 is an elevation view of a thread repair insert, showing the back side of the thread repair insert;
FIG. 5 is an elevation view of a thread repair insert, showing the left side of the thread repair insert;
FIG. 6 is an elevation view of a thread repair insert, showing the right side of the thread repair insert;
FIG. 7 is a plan view of a thread repair insert, showing the top of the thread repair insert;
FIG. 8 is a plan view of a thread repair insert, showing the bottom of the thread repair insert;
FIG. 9 is an enlarged partial top perspective view, taken along line 9 of FIG. 1, of the lower end of the thread repair insert; and,
FIG. 10 is an alternate enlarged partial bottom perspective view, taken along line 10 of FIG. 2, of the lower end of the thread repair insert.
The broken lines in the drawings illustrate portions of the thread repair insert and form no part of the claimed design.

1 Claim, 7 Drawing Sheets



(56)

References Cited

U.S. PATENT DOCUMENTS

6,547,564	B1 *	4/2003	Hansson	A61B 17/863 433/174
7,008,228	B2 *	3/2006	Bjorn	A61C 8/0025 433/173
D577,122	S *	9/2008	Aldecoa	D24/156
D604,851	S *	11/2009	Ishikawa	D24/156
7,845,945	B2 *	12/2010	Canter	A61C 8/0018 433/173
2002/0102146	A1 *	8/2002	Wheeler	F16B 37/127 411/178
2003/0219325	A1 *	11/2003	Schultz	F16B 37/125 411/178
2004/0136807	A1 *	7/2004	Foerster, Jr.	F16B 37/127 411/178
2006/0013671	A1 *	1/2006	Lauderbaugh	F16B 37/127 411/178
2017/0122359	A1 *	5/2017	Foerster, Jr.	B23P 6/00

* cited by examiner




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10