



US00D965454S

(12) **United States Design Patent** (10) **Patent No.:** **US D965,454 S**
Protti (45) **Date of Patent:** **** Oct. 4, 2022**

(54) **AUTOMOTIVE DIAGNOSTIC SCAN TOOL**

(71) Applicant: **Innova Electronics Corporation,**
Irvine, CA (US)

(72) Inventor: **John Protti,** Irvine, CA (US)

(73) Assignee: **Innova Electronics Corporation,**
Irvine, CA (US)

D827,464 S * 9/2018 Hao D10/78
D834,432 S * 11/2018 Wang D10/78
D838,195 S * 1/2019 Wu D10/78
D838,197 S * 1/2019 Wu D10/78
D839,113 S * 1/2019 Xie D10/78
D839,114 S * 1/2019 Xie D10/78
D842,147 S * 3/2019 Xie D10/78
D851,515 S * 6/2019 Zhao D10/78
D852,073 S * 6/2019 Zhao D10/78
D871,943 S * 1/2020 Xie D10/78

(Continued)

(**) Term: **15 Years**

(21) Appl. No.: **29/754,280**

(22) Filed: **Oct. 8, 2020**

(51) **LOC (13) Cl.** **10-04**

(52) **U.S. Cl.**
USPC **D10/78**

(58) **Field of Classification Search**
USPC D10/78, 103, 102, 70, 47; D14/203.7,
D14/186
CPC G01R 15/125; G01R 1/04; G01R 15/002;
G01R 1/0675; G01R 1/06788; H04W
88/05; G01S 3/7865; G08B 21/182
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D502,416 S * 3/2005 Chen D10/78
D532,326 S * 11/2006 Ishii D10/70
D533,095 S * 12/2006 Kaushal D10/78
D534,445 S * 1/2007 Kaushal D10/78
D558,621 S * 1/2008 Rich D10/78
D560,527 S * 1/2008 Rich D10/78
D624,446 S * 9/2010 Chen D10/78
D625,634 S * 10/2010 Chen D10/78
D636,282 S * 4/2011 Yin D10/70
D692,335 S * 10/2013 Waaler D10/78
D698,673 S * 2/2014 Igelmund D10/78
D718,161 S * 11/2014 Derr D10/78
D804,338 S * 12/2017 Protti D10/78
D806,592 S * 1/2018 Protti D10/78

OTHER PUBLICATIONS

Innova 3011 Code Reader—How it Works publication date Feb. 23, 2021, (online) URL: <https://www.youtube.com/watch?v=GwkD3tiKZic> (Year: 2021).*

(Continued)

Primary Examiner — George D. Kirschbaum
Assistant Examiner — Antoinette Martine Suiter
(74) *Attorney, Agent, or Firm* — Stetina Brunda Garred & Brucker


(57) **CLAIM**

The ornamental design for automotive diagnostic scan tool, as shown and described.

DESCRIPTION

FIG. 1 is a front upper perspective view the automotive diagnostic scan tool showing my new design;
FIG. 2 is a top plan view thereof;
FIG. 3 is a side elevational view thereof;
FIG. 4 is a front elevational view thereof;
FIG. 5 is an opposite side elevational view thereof;
FIG. 6 is a rear elevational view thereof; and,
FIG. 7 is a bottom plan view thereof.
The broken lines, and unshaded surfaces bound on all sides by broken lines, represent portions of the article that form no part of the claimed design.

1 Claim, 3 Drawing Sheets



(56)

References Cited

U.S. PATENT DOCUMENTS

D903,515 S * 12/2020 Zhao D10/78
D918,074 S * 5/2021 Zhao D10/78
D918,748 S * 5/2021 Zhao D10/78
D926,609 S * 8/2021 Xie D10/78
D931,127 S * 9/2021 Shao D10/70

OTHER PUBLICATIONS

Does Anyone Know the Severity of this Engine Code . . . ?, Reddit, publication date Jun. 3, 2021, (online) URL: https://www.reddit.com/r/subaru/comments/nrjzah/does_anyone_know_the_severity_of_this_engine_code/ (Year: 2021).*

Innova Electronics Corporation. "Innova 3020d: ABS Scan Tool for OBD2 Vehicles;" 2020.

* cited by examiner




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7