



US0D1065007S

(12)

United States Design Patent

Costle

(10)

Patent No.:

US D1,065,007 S

(45)

Date of Patent:

** Mar. 4, 2025

(54) TIRE REPAIR SYSTEM

(71) Applicant: Illinois Tool Works Inc., Glenview, IL (US)

(72) Inventor: Carey Costle, Tucson, AZ (US)

(73) Assignee: Illinois Tool Works Inc., Glenview, IL (US)

8,251,106 B2 8/2012 Lolli

8,459,150 B2 6/2013 Yoshida

8,596,310 B2 12/2013 Senno

(Continued)

FOREIGN PATENT DOCUMENTS

AR 103628-0001 * 3/2023

AR 103629-0001 * 3/2023

(Continued)

(**) Term:

15 Years

OTHER PUBLICATIONS

(21) Appl. No.: 29/855,274

(22) Filed: Sep. 30, 2022

(51) LOC (15) Cl. 12-16

(52) U.S. Cl. D12/400

(58) Field of Classification Search

USPC D3/273, 274, 276, 282, 302; D12/400; D15/7, 9, 199

CPC B60C 25/16; B60C 29/062; B60S 5/04; B60S 5/046

See application file for complete search history.

“Slime 50158 Flat Tire Repair Kit, Smart Spair Ultra, All-in-One Solution, Repairs and Inflates, Car/Trailer, 10 Min Fix” Mar. 12, 2024, product listing, retrieved Oct. 10, 2024, retrieved from <URL:https://www.amazon.com/Slime-50158-Solution-Repairs-Inflates/dp/B0CXTF2F3G/?th=1> (Year: 2024).*

(Continued)

Primary Examiner — Calvin E Vansant

Assistant Examiner — Pia J Marchetti

(74) Attorney, Agent, or Firm — McAndrews, Held & Malloy, Ltd.

(56) References Cited

U.S. PATENT DOCUMENTS

3,718,238	A	2/1973	Hazard	
3,786,964	A	1/1974	Landen	
4,081,113	A	3/1978	Hazard	
5,104,295	A	4/1992	Wong	
5,156,853	A	10/1992	Werner	
5,381,836	A	1/1995	Braatz	
5,427,145	A	6/1995	Grabenkort	
5,687,777	A	11/1997	Dobson	
D425,913	S	5/2000	Bonzer	
6,789,581	B2	9/2004	Cowan	
D508,058	S *	8/2005	Wu	D15/7
7,789,110	B2	9/2010	Marini	
7,798,183	B2	9/2010	Cegelski	
7,886,783	B2	2/2011	Rindy	
8,251,105	B2	8/2012	Lolli	


(57) CLAIM

The ornamental design for a tire repair system as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a tire repair system; FIG. 2 is a top plan view thereof; FIG. 3 is a bottom plan view thereof; FIG. 4 is a right side elevation view thereof; FIG. 5 is a left side elevation view thereof; FIG. 6 is a rear side elevation view thereof; and, FIG. 7 is a front side elevation view thereof. The broken lines in the drawings illustrate portions of the tire repair system that form no part of the claimed design.

1 Claim, 5 Drawing Sheets



(56)

References Cited

FOREIGN PATENT DOCUMENTS

U.S. PATENT DOCUMENTS

8,631,840 B2 1/2014 Lolli
8,752,595 B2 6/2014 Marini
8,857,477 B2 10/2014 Lolli
D719,352 S * 12/2014 Shitrit D3/905
8,997,802 B2 4/2015 Lolli
9,061,471 B2 6/2015 Marini
9,168,798 B2 10/2015 Eckhardt
9,221,221 B2 12/2015 Lolli
9,272,587 B2 3/2016 Taniguchi
D785,938 S * 5/2017 Ou D3/905
9,868,420 B2 1/2018 Chou
9,914,271 B2 3/2018 Spindler
D841,981 S * 3/2019 Kögel D3/282
D858,995 S * 9/2019 Chang D3/273
D873,011 S * 1/2020 Kao D3/905
10,786,958 B2 9/2020 Lam
10,926,495 B2 2/2021 Spindler
11,034,104 B2 6/2021 Dowel
11,046,129 B2 6/2021 Chou
11,135,792 B2 10/2021 Lam
11,400,667 B2 8/2022 Hong
2010/0108186 A1 5/2010 Yoshida
2011/0155280 A1 6/2011 Eckhardt
2011/0192492 A1 8/2011 Kanenari
2014/0209207 A1 7/2014 Spindler
2014/0209208 A1 7/2014 Taniguchi
2015/0059921 A1 3/2015 Jhou
2016/0271892 A1 9/2016 Eckhardt
2016/0288434 A1 10/2016 Eckhardt
2017/0072648 A1 3/2017 Zaum
2017/0173900 A1 6/2017 Kawatani
2024/0247648 A1 * 7/2024 Costle B29C 73/166

CN 102673533 A 9/2012
CN 203752543 U 8/2014
CN 204278561 U 4/2015
CN 208452350 U 2/2019
CN 208502970 U 2/2019
CN 110131124 A 8/2019
DE 10106468 A1 8/2002
DE 102014205067 A1 9/2015
DE 102019217775 A1 5/2021
EP 2196305 B1 2/2012
EP 2295299 B1 7/2012
EP 2058112 B1 5/2015
EP 2807018 B1 10/2018
JP 2006103144 A 4/2006
WO 2006038640 A1 4/2006
WO 2009065653 A1 5/2009

OTHER PUBLICATIONS

“Slime 50159 Flat Tire Repair Kit, Smart Spair Ultra, All-in-one Solution, Repairs and Inflates, Truck/SUV, 15 Min Fix” Mar. 12, 2024, product listing, retrieved Oct. 10, 2024, retrieved from <URL:https://www.amazon.com/Slime-50158-Solution-Repairs-Inflates/dp/B0CXTMD1WS/> (Year: 2024).*

Slime Flat Tire Repair Kit, AutoZone—Auto Parts/Suspension, Steering, Tire and Wheel/Tire Maintenance and Repair/Tire Repair Kit, Part #50122, SKU #562272 (9 pages).

* cited by examiner




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7