Vong

[45] ** Jul. 17, 1979

[54]	RECORD PLAYER			
[76]	Inventor:	Hio T. Vong, 179/810 Connaught Rd. West, Cheung Ka Industrial Bldg., 19th Floor, Block A, West Point, Hong Kong		
[**]	Term:	14 Years		
[21]	Appl. No.:	891,483		
[22]	Filed:	Mar. 29, 1978		
[30] Foreign Application Priority Data				
Feb. 28, 1978 [GB] United Kingdom 983529/78				
[51] Int. Cl				
[56] References Cited				
U.S. PATENT DOCUMENTS				
	30,608 3/1 37,107 10/1	T3.1.4.74.4		

3.042.411	7/1962	Weise
4,098,512	7/1978	Takizawa 274/15 R

OTHER PUBLICATIONS

Radio Shack, 1976, Electronics Catalog, p. 37, Turntable, top right of page.

Montgomery Ward, Christmas 1977, ©1977, p. 362, item D, Phonograph.

Primary Examiner—Bernard Ansher Attorney, Agent, or Firm—Milton J. Wayne

[57] CLAIM

The ornamental design for a record player, substantially as shown and described.

DESCRIPTION


FIG. 1 is a top perspective view of a record player showing my design;


FIG. 2 is a left side elevation view thereof;


FIG. 3 is a rear elevation view thereof;


FIG. 4 is a bottom plan view thereof; and

FIG. 5 is a perspective view corresponding to FIG. 1, with the cover removed from the turntable and pickup arm of the record player.











F19.4.

Jul. 17, 1979





UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. DES. 252, 392

DATED

July 17, 1979

INVENTOR(S): Hoi T. Vong

It is certified that error appears in the above—identified patent and that said Letters Patent is hereby corrected as shown below:

In the title page, the inventor's first name has been misspelled: "Hio" should be --Hoi--.

In the title page, part of the inventor's address is incorrectly set out: "179/810" should be --179/180--.

Bigned and Sealed this

Eighteenth Day of March 1980

(SEAL)

Attest:

SIDNEY A. DIAMOND

Attesting Officer

Commissioner of Patents and Trademarks