

[54] **GOLF CLUB CLEANER**

[76] Inventor: **Richard W. Dobyns**, 1351 Graymill Dr., Scotch Plains, N.J. 07076

[**] Term: **14 Years**

[21] Appl. No.: **185,785**

[22] Filed: **Sep. 10, 1980**

[51] Int. Cl. **D15-05**

[52] U.S. Cl. **D32/1**

[58] Field of Search **D32/1-15, D32/25-34; 15/1, 21 B, 21 C, 104 R, 104.92**

3,583,018 6/1971 Fink 15/104.92

3,872,534 3/1975 Hoag 15/21 B

3,950,810 4/1976 Harkess 15/21 C

4,069,536 1/1978 Hartz et al. 15/104.92

Primary Examiner—James R. Largen

[57] **CLAIM**

The ornamental design of a golf club cleaner, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a housing for a golf club cleaner showing my new design;

FIG. 2 is a front view thereof;

FIG. 3 is a top view thereof;

FIG. 4 is a rear view thereof;

FIG. 5 is a left side view thereof; and

FIG. 6 is a right side view thereof.

The broken line representation of a golf club in FIG. 6 is for purposes of illustration only.

[56] **References Cited**

U.S. PATENT DOCUMENTS

D. 185,492 6/1959 Dreyfuss D32/1

D. 237,005 9/1975 Akel D32/1

3,101,089 8/1963 Brown et al. 132/186

3,332,099 7/1967 Reiter 15/21 R




Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6

