

[54] DUAL UTILITY SERVICES CONSOLE OR MARINAS

[76] Inventor: H. Stanley Wyatt, 237 W. Oceanview Ave., Norfolk, Va. 23503

[\*\*] Term: 14 Years

[21] Appl. No.: 607,588

[22] Filed: May 7, 1984

[52] U.S. Cl. .... D13/40; D23/1

[58] Field of Search ..... D13/24, 25, 27-31, D13/13, 40, 41; D174/37, 38; D23/1; 361/331, 332, 334, 363, 364

[56] References Cited

U.S. PATENT DOCUMENTS

|            |         |               |       |           |
|------------|---------|---------------|-------|-----------|
| D. 237,718 | 11/1975 | Bozich        | ..... | D13/40    |
| D. 270,831 | 10/1893 | Jensen        | ..... | D13/40    |
| 3,891,899  | 6/1975  | Sparling      | ..... | 361/334   |
| 4,307,436  | 12/1981 | Eckart et al. | ..... | 361/334 X |

Primary Examiner—Susan J. Lucas  
Attorney, Agent, or Firm—William F. Frank

[57] CLAIM

The ornamental design for a dual utility services console for marinas, as shown and described.

DESCRIPTION


FIG. 1 is a top, front perspective view of the dual utility services console for marinas showing my new design, the rear being identical thereto.

FIG. 2 is a left side elevational view thereof, the right side being a mirror image.

FIG. 3 is a top, front perspective view thereof showing the receptacle covers in open condition, the rear being identical in the open condition.

FIG. 4 is a front elevational view thereof, the rear being a mirror image.

FIG. 5 is a front elevational view thereof showing the receptacle covers in open condition, the rear being a mirror image.






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5