### United States Patent [19] Baldwin

[11] Patent Number: Des. 314,494 Date of Patent: \*\* Feb. 12, 1991 [45]

#### **CAR EXTRACTION TOOL** [54]

- Inventor: Randolf O. Baldwin, 411 Hollyberry [76] La., Lugoff, S.C. 29078
- [\*\*] Term: 14 Years
- Appl. No.: 104,032 [21]
- Filed: [22] Oct. 2, 1987 [52] Field of Search ...... D8/14, 51, 98; 24/71.3; [58]

4,549,423	10/1985	Masui 72/295
4,555,926	12/1985	Bieli-Möschlin 72/392
4,800,628	1/1989	Farnsworth 24/71.3

Primary Examiner-Bruce W. Dunkins Assistant Examiner-M. A. Hannon Attorney, Agent, or Firm-Jerry T. Kearns

#### [57] **CLAIM**

The ornamental design for a car extraction tool, as shown and described.

72/478, 392, 461, 295

#### [56] **References** Cited U.S. PATENT DOCUMENTS

D. 297,396	8/1988	Schwalbe	D8/14
1,326,426	12/1919	Shea	D8/51
4,282,740	8/1981	Specktor	72/461
		Meek	

### DESCRIPTION

FIG. 1 is a front elevational view of a car extraction tool showing my new design; FIG. 2 is a rear elevational view thereof; FIG. 3 is a left side elevational view thereof; FIG. 4 is a right side elevational view thereof; FIG. 5 is a top plan view thereof; and, FIG. 6 is a bottom plan view thereof.







## U.S. Patent Feb. 12, 1991 Sheet 1 of 2 Des. 314,494

•

.

.

•





.





.

Fig. 2

# U.S. Patent Feb. 12, 1991 Sheet 2 of 2 Des. 314,494

-



. ۴ ٦

.



**N** 

-

Fig. 3

Fig. 4



.





.

•



### UNITED STATES FATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

**PATENT NO.** : Des. 314,494

DATED : February 12, 1991

INVENTOR(S) : Randolf O. Baldwin

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE: The Inventor's name should read;

```
Item [76] Randolph O. Baldwin
```

