



US00D369770S

United States Patent [19]

Sawyer et al.

[11] Patent Number: **Des. 369,770**

[45] Date of Patent: ****May 14, 1996**

[54] PUNCTURE REPAIR PLUG

[76] Inventors: **Robert J. Sawyer; Connie A. Slone,**
both of 12104 Woodside Dr., Riverview,
Fla. 33569

[**] Term: **14 Years**

[21] Appl. No.: **37,300**

[22] Filed: **Apr. 10, 1995**

[52] U.S. Cl. **D12/153**

[58] Field of Search D12/153; 81/15.7;
152/367, 368, 369; 156/97

[56] **References Cited**

U.S. PATENT DOCUMENTS

684,647	10/1901	Madsen	81/15.7
2,727,554	12/1955	Westfall	152/370
2,803,284	8/1957	Mullen	D12/153
4,096,901	6/1978	Reichenbach	152/370
4,802,388	2/1989	Roberts	81/15.7
4,827,998	5/1989	Stanfa	152/368

4,923,543	5/1990	Koch et al.	156/97
5,053,089	10/1991	Ristich	152/370
5,062,323	11/1991	Roberts et al.	81/15.7
5,425,407	6/1995	Archuleta et al.	152/370

Primary Examiner—Alan P. Douglas
Assistant Examiner—S. Snapp

[57] **CLAIM**

The ornamental design for the puncture repair plug, as shown and described.

DESCRIPTION

FIG. 1 is a reduced front elevational view of the puncture repair plug showing our new design in a use position, the broken line showing of a portion of a tire for illustrative purposes only and forming no part of the claimed design; FIG. 2 is a rear elevational view thereof; FIG. 3 is a left side elevational view thereof; FIG. 4 is a right side elevational view thereof; FIG. 5 is an enlarged top plan view thereof; and, FIG. 6 is an enlarged bottom plan view thereof.

1 Claim, 3 Drawing Sheets




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

