



US00D378547S

United States Patent [19]

Holland

[11] Patent Number: Des. 378,547
[45] Date of Patent: **Mar. 25, 1997

[54] LEATHER SHOEHORN

[75] Inventor: John M. Holland, Larkspur, Calif.

[73] Assignee: Holland Brothers, San Francisco, Calif.

[**] Term: 14 Years

[21] Appl. No.: 44,290

[22] Filed: Sep. 21, 1995

[52] U.S. Cl. D2/642

[58] Field of Search D2/641, 642, 643; 223/113, 114, 115, 116, 117, 118; D3/201, 208, 210

[56] References Cited

U.S. PATENT DOCUMENTS

| | | | |
|------------|---------|---------------|----------|
| D. 58,797 | 8/1921 | Mayhew | D2/642 |
| D. 160,905 | 11/1950 | Tarrant | D2/642 X |
| D. 223,974 | 6/1972 | Tsutsui | D3/210 X |
| D. 224,365 | 7/1972 | Lewis | D2/642 |
| D. 238,976 | 2/1976 | Dolas | D3/208 |
| D. 290,063 | 6/1987 | Wright | D2/642 |
| 1,522,922 | 1/1925 | Smiley | 223/118 |
| 2,483,714 | 10/1949 | Shaffer | D2/642 X |
| 3,088,639 | 5/1963 | Sexton | D2/642 X |
| 3,436,000 | 4/1969 | Batista | 223/118 |
| 4,290,539 | 9/1981 | Lowery | D2/642 X |

Primary Examiner—Paula A. Mortimer

Attorney, Agent, or Firm—Cushman Darby & Cushman IP Group of Pillsbury Madison & Sutro LLP

[57] CLAIM

The ornamental design for a leather shoehorn, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a leather shoehorn showing my new design; the looped member is broken away for purposes of illustration;

FIG. 2 is a top plan view thereof, the bottom plan view is a mirror image;

FIG. 3 is a side elevational view thereof, the opposite side is a mirror image;

FIG. 4 is a front elevational view of a second embodiment of a leather showhorn showing my new design, the bottom is a mirror image, the only difference being the absence of the looped member and corresponding through-hole;

FIG. 5 is an end elevational view thereof, the view shown being from the broad end of the shoehorn of my design; and,

FIG. 6 is an end elevational view thereof, the view shown being from the narrow end of the shoehorn of my design.

The loop member in FIGS. 1, 2 and 3 is shown broken away for ease of illustration.

FIGS. 4, 5, and 6 show an alternate design wherein the loop member and the hole on the narrow end of the shoehorn are absent.

1 Claim, 1 Drawing Sheet



