



US00D392362S

United States Patent [19]
Ridgeway

[11] **Patent Number:** **Des. 392,362**
[45] **Date of Patent:** ****Mar. 17, 1998**

[54] **COMBINED CIGAR STAND AND GOLF BALL DIVOT REPAIR TOOL**

[76] **Inventor:** **Bill Ridgeway, 5633 Sorrento Dr., Long Beach, Calif. 90803**

[**] **Term:** **14 Years**

[21] **Appl. No.:** **61,246**

[22] **Filed:** **Nov. 19, 1996**

[51] **LOC (6) Cl.** **21-02**

[52] **U.S. Cl.** **D21/234; D27/183**

[58] **Field of Search** **D21/234; D27/183; D6/417; 131/187, 188, 257, 240.1**

[56] **References Cited**

U.S. PATENT DOCUMENTS

D. 375,815	11/1996	Kagasoff	D21/234
D. 379,551	5/1997	Hubbard	D27/183
3,001,529	9/1961	Watson	D27/183 X

Primary Examiner—Ted Shooman
Assistant Examiner—Mitchell I. Siegel
Attorney, Agent, or Firm—Fulwider Patton Lee & Utecht, LLP


[57] **CLAIM**

The ornamental design for a combined cigar stand and golf ball divot repair tool, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view showing my new design; FIG. 2 is a front elevational view thereof, but in enlarged scale; FIG. 3 is a left end view thereof, but in enlarged scale, the opposite side being identical; FIG. 4 is a top plan view thereof, but in enlarged scale; and, FIG. 5 is a bottom plan view thereof, but in enlarged scale.

1 Claim, 1 Drawing Sheet






FIG. 1




FIG. 2

FIG. 3




FIG. 4




FIG. 5

