



US00D407659S

# United States Patent [19] Utrera

[11] **Patent Number: Des. 407,659**  
[45] **Date of Patent: \*\*Apr. 6, 1999**

[54] **SERVICE INDICATOR**  
[75] Inventor: **Ivan R. Utrera**, Littleton, Colo.  
[73] Assignee: **Rodizio Restaurants International, Inc.**, Littleton, Colo.  
[\*\*] Term: **14 Years**  
[21] Appl. No.: **90,125**  
[22] Filed: **Jun. 29, 1998**  
[51] **LOC (6) Cl. .... 10-05**  
[52] **U.S. Cl. .... D10/114**  
[58] **Field of Search .... D10/104, 106, D10/109, 114, 121; D26/93, 105; 116/202, 205; 340/473, 321; 362/157, 183, 414, 806**

D. 328,571 8/1992 Hauser ..... D10/114  
D. 349,071 7/1994 Fields et al. .... D10/114  
D. 352,964 11/1994 Schlotterback ..... D10/114  
D. 374,834 10/1996 Rusch ..... D10/114  
5,489,887 2/1996 Porras ..... D10/114

*Primary Examiner*—Marcus A. Jackson  
*Attorney, Agent, or Firm*—Sheridan Ross, P.C.

### [57] CLAIM


The ornamental design for a service indicator, as shown and described.


### DESCRIPTION

FIG. 1 is a perspective view of a service indicator showing my new design, wherein the lined pattern indicates the colors red, brown and green;  
FIG. 2 is a side elevational view thereof, with the opposite sides being a mirror image;  
FIG. 3 is a top plan view thereof; and,  
FIG. 4 is a bottom plan view thereof.


[56] **References Cited**  
U.S. PATENT DOCUMENTS  
D. 287,106 12/1986 Wade ..... D10/114

**1 Claim, 1 Drawing Sheet**






**Fig. 1**



**Fig. 2**

**Fig. 3**



**Fig. 4**

