



US00D425812S

United States Patent [19]

[11] **Patent Number: Des. 425,812**

Bodo

[45] **Date of Patent: ** May 30, 2000**

[54] **WARNING TRIANGLE**

Primary Examiner—Marcus A. Jackson

[76] Inventor: **Brooke Bodo**, 523 Beechwood Drive,
#19 Kitchener, Ontario, Canada, N2T
2G7

[57] **CLAIM**

The ornamental design for a warning triangle, as shown and described.

[**] Term: **14 Years**

DESCRIPTION

[21] Appl. No.: **29/109,662**

FIG. 1 is a front elevational view of the warning triangle of the present invention;

[22] Filed: **Aug. 19, 1999**

FIG. 2 is a rear elevational view of the warning triangle of FIG. 1;

[51] **LOC (7) Cl.** **10-05**

FIG. 3 is a left side elevational view of the warning triangle of FIG. 1;

[52] **U.S. Cl.** **D10/114**

[58] **Field of Search** D10/109, 111,
D10/114, 121; 116/63 P, 63 T; 362/191,
196, 197, 198, 199, 200, 201, 202

FIG. 4 is a right side elevational view of the warning triangle of FIG. 1;

FIG. 5 is a top plan view of the warning triangle of FIG. 1; and,


[56] **References Cited**

FIG. 6 is a bottom plan view of the warning triangle of FIG. 1.

U.S. PATENT DOCUMENTS

D. 340,001 10/1993 Watkins D10/114
D. 391,881 3/1998 Youseph D10/114

1 Claim, 3 Drawing Sheets






FIG. 1




FIG. 6




FIG. 5




FIG. 2




FIG. 3




FIG. 4