



US00D437053S

(12) **United States Design Patent**
Mirabal, Jr.

(10) **Patent No.:** **US D437,053 S**

(45) **Date of Patent:** **** Jan. 30, 2001**

(54) **BEDPAN LINER**

(76) Inventor: **Bobby Mirabal, Jr.**, 2002 Craig,
Corpus Christi, TX (US) 78405

(**) Term: **14 Years**

(21) Appl. No.: **29/109,676**

(22) Filed: **Aug. 19, 1999**

(51) **LOC (7) Cl.** **24-02**

(52) **U.S. Cl.** **D24/132**

(58) **Field of Search** D24/123, 132;
4/144.1, 144.2, 315, 450, 451, 452, 484,
DIG. 18; D3/244; D9/305; 150/100, 150,
155; 383/72, 75

(56) **References Cited**

U.S. PATENT DOCUMENTS

D. 136,550	*	10/1943	Hiltensbrand	D3/244
D. 228,966	*	10/1973	Mills	D24/132
1,681,922	*	8/1928	Boch	D3/244
3,249,950	*	5/1966	Wilson	4/452
3,377,631	*	4/1968	Whitney	D24/132

* cited by examiner

Primary Examiner—Alan P. Douglas

Assistant Examiner—Reid Hecker

(57) **CLAIM**

The ornamental design for a bedpan liner, as shown and described.

DESCRIPTION

FIG. 1 is a left side elevational view of the bedpan liner of the present invention;

FIG. 2 is a right side elevational view of the bedpan liner of FIG. 1;

FIG. 3 is a rear elevational view of the bedpan liner of FIG. 1;


FIG. 4 is a front elevational view of the bedpan liner of FIG. 1;

FIG. 5 is a top plan view of the bedpan liner of FIG. 1; and, FIG. 6 is a bottom plan view of the bedpan liner of FIG. 1.

The broken line shown proximate the top edge of the claimed design is indicative of elastic stitching.

The broken lines showing of a bed pan as shown in FIGS. 1 and 5 are for illustrative purposes only and form no part of the claimed design.

1 Claim, 2 Drawing Sheets






Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6