



US00D446477B1

(12) **United States Design Patent** (10) **Patent No.:** **US D446,477 S**
Netz et al. (45) **Date of Patent:** **** Aug. 14, 2001**

(54) **MOTORCYCLE DERBY COVER**

(75) Inventors: **Louis N. Netz**, Grafton; **David P. Bozeman**, Milwaukee, both of WI (US)

(73) Assignee: **Harley-Davidson Motor Company Group, Inc.**, Milwaukee, WI (US)

(**) Term: **14 Years**

(21) Appl. No.: **29/090,198**

(22) Filed: **Jul. 2, 1998**

(51) **LOC (7) Cl.** **12-11**

(52) **U.S. Cl.** **D12/126**

(58) **Field of Search** D12/110, 114,
D12/126; 280/288.4; 180/219; D15/5; 123/90.37,
90.38, 143 C, 195 C, 198 E

(56) **References Cited**

U.S. PATENT DOCUMENTS

D. 294,923 * 3/1988 Nagy D12/126

OTHER PUBLICATIONS

Drag Specialties, Derby Cover No. DS-375700 and DS-375600, pp. 217 and 707 1995.*

Genuine Parts & Accessories 1994 Catalog—p. 97.

Custom Chrome 1994 Catalog—p. 439.

1994 Motorcycles—p. 6.

* cited by examiner

Primary Examiner—Alan P. Douglas

Assistant Examiner—Linda Brooks

(74) *Attorney, Agent, or Firm*—Michael Best & Friedrich LLP

(57) **CLAIM**

The ornamental design for a motorcycle derby cover, as shown and described.

DESCRIPTION

FIG. 1 is a left side view of the motorcycle derby cover embodying the present invention while in use.

FIG. 2 is an enlarged left side view of the design shown in FIG. 1; and,

FIG. 3 is an enlarged perspective view of the design shown in FIG. 1.



The present application is directed to the design illustrated in the drawings. The other features of the drawings, such as the motorcycle shown in FIG. 1, are not considered part of the design sought to be patented, and have accordingly been shown in broken lines.

The broken lines which define the boundaries of the claimed design form no part thereof.

The design sought to be patented is not visible in the top, bottom, front, and rear views. Accordingly, these views have been omitted.

The right side view of the design is not visible in its normal or intended use because it is substantially obscured by the motorcycle transmission. Therefore, the right side view is not a matter of ornamental concern, and has been omitted from the drawings.

1 Claim, 3 Drawing Sheets






Fig. 1




Fig. 2




Fig. 3