

US00D492567S1

(12) United States Design Patent (10) Patent No.:

Jimenez et al.

D477,519 S

* cited by examiner

US D492,567 S

(45) Date of Patent:

Jul. 6, 2004

(54)	SAW	
(75)	Inventors:	Eduardo J. Jimenez, Manalapan, NJ (US); Joseph L. Kapushion, Erie, CO (US)
(73)	Assignee:	KC Holdings, PLLC
(**)	Term:	14 Years
(21)	Appl. No.: 29/182,607	
(22)	Filed:	May 30, 2003
(51)	LOC (7) Cl 08-03	
(52)	U.S. Cl	D8/96
(58)	Field of Search	
D8/98, 99, 107; 30/506, 508, 509, 511,		
513, 517, 522		
(56) References Cited		
U.S. PATENT DOCUMENTS		
	D370,610 S	* 6/1996 Neyton D8/96
	D403,224 S	* 12/1998 Martin et al
	D409,892 S	* 5/1999 Juhlin
	6,070,330 A	* 6/2000 Phelon et al 30/513

Primary Examiner—Philip S. Hyder

(74) Attorney, Agent, or Firm-Wolff & King, PLLC; Kevin A. Wolff; Eric G. King

(57)**CLAIM**

The ornamental design for a saw, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of the saw showing my new design looking upward at the front and left side thereof, and showing a saw blade and through holes in the saw frame structure in broken lines;

FIG. 2 is a left elevation view of the saw and showing a saw blade and through holes in the saw frame structure in broken lines;

FIG. 3 is a right elevation view of the saw and showing a saw blade and through holes in the saw frame structure in broken lines;


FIG. 4 is a front elevation view of the saw;


FIG. 5 is a rear elevation view of the saw;


FIG. 6 is a top plan view of the saw; and,

FIG. 7 is a bottom plan view of the saw and showing a saw blade and a tension adjustment through hole in broken lines. The broken lines showing the saw blade, through holes in the saw frame structure, and the tension adjustment through hole are for illustrative purposes only and forms no part of the claimed design.

1 Claim, 5 Drawing Sheets










FIG. 4




FIG. 5

