



US00D515959S

(12) **United States Design Patent** (10) **Patent No.:** **US D515,959 S**  
**Nelson et al.** (45) **Date of Patent:** **\*\* Feb. 28, 2006**

(54) **POWER FAILURE RECEPTACLE WARNING LIGHT**

(75) Inventors: **Russel J. Nelson**, Crystal Lake, IL (US); **Jeffery K. Bovee**, Richmond, IL (US)

(73) Assignee: **Intermatic Incorporated**, Spring Grove, IL (US)

(\*\*) Term: **14 Years**

(21) Appl. No.: **29/231,935**

(22) Filed: **Jun. 10, 2005**

(51) **LOC (8) Cl.** ..... **10-05**

(52) **U.S. Cl.** ..... **D10/114; D26/26**

(58) **Field of Classification Search** ..... D26/87, D26/86, 85, 82, 79, 78, 76, 75, 72, 26; D13/160, D13/139.6, 139.3, 139.1; D10/114; 439/651, 439/650, 539, 538, 107; 362/95, 20; 361/42, 361/43; 174/67, 66, 53

See application file for complete search history.

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

3,739,226 A	6/1973	Seiter et al.	
D254,514 S	* 3/1980	Nicholl et al. ....	D26/26
D269,431 S	* 6/1983	Doyle et al. ....	D13/139.3
D273,048 S	* 3/1984	Chan .....	D26/37
D274,368 S	* 6/1984	Skarman .....	D26/26
4,514,789 A	4/1985	Jester	
4,631,649 A	12/1986	McCue et al.	
D288,245 S	* 2/1987	Corder et al. ....	D26/26
D343,018 S	* 1/1994	Garrity .....	D26/37
D347,594 S	* 6/1994	Davis et al. ....	D10/104

5,473,517 A	12/1995	Blackman	
5,713,655 A	2/1998	Blackman	
5,833,350 A	11/1998	Moreland	
5,851,061 A	12/1998	Hegarty	
D413,862 S	* 9/1999	Huang et al. ....	D13/139.3
6,000,807 A	12/1999	Moreland	
6,010,228 A	1/2000	Blackman et al.	
6,045,232 A	4/2000	Buckmaster	
D429,694 S	* 8/2000	Schlessinger et al. ....	D13/154
6,095,850 A	* 8/2000	Liu .....	439/488
6,437,700 B1	8/2002	Herzfeld et al.	
6,805,469 B1	10/2004	Barton	
2004/0218379 A1	11/2004	Barton	
2005/0012633 A1	1/2005	Yoon	
2005/0030685 A1	* 2/2005	DiSalvo .....	361/42

\* cited by examiner

*Primary Examiner*—Cathron C. Brooks

*Assistant Examiner*—Austin Murphy

(74) *Attorney, Agent, or Firm*—Brinks Hofer Gilson & Lione


(57) **CLAIM**

We claim the ornamental design for a power failure receptacle warning light, as shown and described.

**DESCRIPTION**

FIG. 1 is a top perspective view of a power failure receptacle warning light of the present invention; FIG. 2 is a front view thereof; FIG. 3 is a rear view thereof; FIG. 4 is a first side view thereof; FIG. 5 is a second side view thereof; FIG. 6 is a third side view thereof; and, FIG. 7 is a fourth side view thereof.

**1 Claim, 3 Drawing Sheets**






Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7