



US00D521587S

(12) **United States Design Patent** (10) **Patent No.:** **US D521,587 S**
Smith (45) **Date of Patent:** **** May 23, 2006**

(54) **COMBINED TIMEPIECE, BOTTLE OPENER, AND GOLF REPAIR TOOL**

(75) Inventor: **Christopher Paul Smith**, Ardmore, PA (US)

(73) Assignee: **Christopher P. Smith**, Rosemont, PA (US)

(**) Term: **14 Years**

(21) Appl. No.: **29/225,918**

(22) Filed: **Mar. 22, 2005**

(51) **LOC (8) Cl.** **21-02**

(52) **U.S. Cl.** **D21/789; D8/34; D8/356; D10/31**

(58) **Field of Classification Search** D21/789, D21/793; 473/286, 408; D8/33-43, 356, D8/357; D10/31, 33, 37; D14/192; 362/119, 362/253

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D318,625 S	*	7/1991	Stowell		D10/31
D348,402 S	*	7/1994	McDonald		D10/31
D403,389 S	*	12/1998	Kim		D21/793
D425,164 S	*	5/2000	Tate		D21/793
D432,027 S	*	10/2000	Fox et al.		D10/31
6,273,582 B1	*	8/2001	Taggart et al.		362/119
D478,011 S	*	8/2003	Cooper		D10/31
D479,221 S	*	9/2003	Wong		D14/192
D502,497 S	*	3/2005	Tien		D18/7
D504,306 S	*	4/2005	Chisolm		D8/356

* cited by examiner

Primary Examiner—Mitchell Siegel

(74) *Attorney, Agent, or Firm*—Jean Paul Cass

(57) **CLAIM**

The ornamental design for a combined timepiece, bottle opener, and golf repair tool, as shown and described in the accompanying figures.

DESCRIPTION

FIG. 1 is a front perspective view of a combined timepiece, bottle opener, and golf repair tool according to the present invention;

FIG. 2 is a rear perspective view of the combined timepiece, bottle opener, and golf repair tool of FIG. 1 showing the bottle opener;

FIG. 3 is a front view of the combined timepiece, bottle opener, and golf repair tool of FIG. 1;

FIG. 4 is a rear view of the combined timepiece, bottle opener, and golf repair tool of FIG. 1 from the opposite side of FIG. 3;

FIG. 5 is a first side view of the combined timepiece, bottle opener, and golf repair tool of FIG. 1;

FIG. 6 is a second side view of the combined timepiece, bottle opener, and golf repair tool being opposite that of FIG. 5;

FIG. 7 is a top view of the combined timepiece, bottle opener, and golf repair tool being of FIG. 3; and,

FIG. 8 is a bottom view of the combined timepiece, bottle opener, and golf repair tool being opposite the view of FIG. 7.

The portion of the combined timepiece, bottle opener, and golf repair tool, including the dial, and the button are all shown in phantom broken lines to indicate that these features form no part of the claimed design.

1 Claim, 4 Drawing Sheets




FIG. 1




FIG. 2




FIG. 3





FIG. 4






FIG. 5




FIG. 6




FIG. 7




FIG. 8