



US00D590472S

(12) **United States Design Patent**
Penton

(10) **Patent No.:** **US D590,472 S**

(45) **Date of Patent:** **** Apr. 14, 2009**

(54) **HAND-HELD TOOL FOR REPAIRING GOLF PITCH MARKS**

(76) Inventor: **Hugh V. Penton**, 800 Grand Ave., Suite A-14, Carlsbad, CA (US) 92008

(**) Term: **14 Years**

(21) Appl. No.: **29/308,785**

(22) Filed: **Jul. 9, 2008**

(51) **LOC (9) Cl.** **21-02**

(52) **U.S. Cl.** **D21/793**

(58) **Field of Classification Search** D21/789,
D21/793; 473/282, 286, 391, 408; 135/16;
194/51

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

5,211,395	A *	5/1993	Liao	473/391
5,261,434	A *	11/1993	Fodero	135/16
5,437,449	A *	8/1995	Zink	473/286
5,765,647	A *	6/1998	Hood	473/408
5,782,443	A *	7/1998	La Fontaine	473/282
5,816,633	A *	10/1998	Odom	294/51
5,839,972	A *	11/1998	Swanson	473/286
6,048,274	A *	4/2000	Lesage	473/286

6,309,308	B1 *	10/2001	Bennett	473/282
D456,475	S *	4/2002	Aldrich	D21/793
D476,054	S *	6/2003	Palmisciano, Jr.	D21/793
2002/0132679	A1 *	9/2002	Wilde et al.	473/282
2004/0038755	A1 *	2/2004	Laux et al.	473/408

* cited by examiner

Primary Examiner—Mitchell I Siegel

(74) *Attorney, Agent, or Firm*—Morland C. Fischer

(57) **CLAIM**

The ornamental design for a hand-held tool for repairing golf pitch marks, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view showing the front, top and right side of a hand-held tool for repairing golf pitch marks which forms my new design;

FIG. 2 is a front elevational view thereof;


FIG. 3 is a rear elevational view thereof;

FIG. 4 is a right side elevational view thereof, this view and the opposite left side elevation view being mirror images;

FIG. 5 is a top plan view thereof; and,

FIG. 6 is a bottom plan view thereof.

1 Claim, 2 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6