



US00D700118S

(12) **United States Design Patent**  
**Hardin et al.**

(10) **Patent No.:** **US D700,118 S**

(45) **Date of Patent:** **\*\* Feb. 25, 2014**

(54) **STEERING WHEEL FOR A MOTOR VEHICLE**

(75) Inventors: **Christian M. Hardin**, Waterford, MI (US); **Sandeep Premkumar**, Fort Wayne, IN (US); **Eric J. Hanson**, Valparaiso, IN (US); **Kurt Garcia**, Juarez (MX); **Andres J. Flores**, Juarez (MX); **Gary C. Bryant**, Chillicothe, IL (US); **Robert B. Riggs**, Canton, MI (US); **Francisco James**, El Paso, TX (US); **Christopher D. Godfrey**, Leo, IN (US); **Kurt A. Ringger**, Bluffton, IN (US); **Robert P. Scott**, Novi, MI (US)

(73) Assignee: **Caterpillar Inc.**, Peoria, IL (US)

(\*\*) Term: **14 Years**

(21) Appl. No.: **29/430,956**

(22) Filed: **Aug. 31, 2012**

**Related U.S. Application Data**

(62) Division of application No. 29/381,463, filed on Dec. 20, 2010, now Pat. No. Des. 673,487.

(51) **LOC (10) Cl.** ..... **12-16**

(52) **U.S. Cl.**  
USPC ..... **D12/176**

(58) **Field of Classification Search**  
USPC ..... D12/176; 74/552, 558, 5  
See application file for complete search history.

(56) **References Cited**

**U.S. PATENT DOCUMENTS**

D206,377 S	12/1966	Ornas, Jr. et al.	
D216,543 S	2/1970	Steele	
D235,862 S	7/1975	Miller	
D277,374 S	1/1985	Koinuma	
D462,039 S *	8/2002	Larocque	D12/176

D472,858 S *	4/2003	Pfeiffer et al.	D12/176
D516,477 S *	3/2006	Tomasson et al.	D12/176
D532,351 S	11/2006	Saito	
D552,520 S	10/2007	Maezono et al.	
D559,158 S *	1/2008	Garcia	D12/176
D564,952 S *	3/2008	Shinshima et al.	D12/176
D564,953 S *	3/2008	Tanaka	D12/176
D565,485 S *	4/2008	Schafmeister	D12/176
D573,518 S	7/2008	Day et al.	
D593,009 S	5/2009	Dammkoehler et al.	
D635,070 S *	3/2011	Granata	D12/176
D651,543 S *	1/2012	Ali et al.	D12/176
D653,594 S *	2/2012	Frank et al.	D12/176

(Continued)

**OTHER PUBLICATIONS**

Photo of 2010 Ford Fusion steering wheel, accessed May 13, 2010  
<http://consumerguideauto.howstuffworks.com/2010-ford-fusion-4.htm?photo=1732710&perspective=interior>.

(Continued)

*Primary Examiner* — Katrina A Betton

(74) *Attorney, Agent, or Firm* — Finnegan, Henderson, Farabow, Garrett & Dunner LLP


(57) **CLAIM**

The ornamental design for a steering wheel for a motor vehicle, as shown and described.

**DESCRIPTION**

FIG. 1 is a front view of a steering wheel for motor vehicle showing our new design;  
FIG. 2 is a front view thereof; and,  
FIG. 3 is a right side view, the left side view being a mirror image thereof. The rear, top and bottom views are apparent from FIG. 3.  
In drawing FIGS. 1 and 3, the broken lines depict portions of a motor vehicle dashboard and form no part of the claimed design.

**1 Claim, 3 Drawing Sheets**



(56)

**References Cited**

U.S. PATENT DOCUMENTS


D666,131 S \* 8/2012 Gasevski et al. .... D12/176  
 D688,606 S \* 8/2013 Balko et al. .... D12/176  
 2002/0158448 A1\* 10/2002 Okonkwo ..... 280/728.2

OTHER PUBLICATIONS


Photo of late 1960s Ford Mustang steering wheel, accessed May 13, 2010 <http://www.mustangmasters.com/featured.asp>.  
 Photo of early 2000s Ford Ka steering wheel, accessed May 13, 2010 [http://www.quadconversions.com/ka-body-styling-kit/ford\\_ka\\_body\\_styling\\_kit\\_bumpers.htm](http://www.quadconversions.com/ka-body-styling-kit/ford_ka_body_styling_kit_bumpers.htm).  
 Photo of Vehicle Improvement Products (VIP steering wheel), accessed 5/13/21010 <http://www.customrigsmag.com/buyers-guide-steering-wheels/>.  
 Photo of Grant Products steering wheel, accessed May 13, 2010 <http://www.customrigsmag.com/buyers-guide-steering-wheels/>.  
 Photo of Vehicle Improvement Products manufactured steering wheel for Mack Trucks, accessed May 13, 2010 <http://www.vipwheels.com/WEB%20PAGES/OEM.products.htm>.  
 Photo of 2009 Audi A4 steering wheel, accessed May 13, 2010.

<http://blogs.edmunds.com/roadtests/2009/09/2009-audi-a4-avant-the-steering-wheel-and-the-scream.html>.  
 Photo of Chevy S-10 sport steering wheel, accessed May 13, 2010 <http://www.customcutgrafix.com/hoopty>.  
 Photo of 1984 Chevy C10 steering wheel, accessed May 13, 2010 <http://67-72chevytrucks.com/vboard/showthread.php?t=318363>.  
 Photo of 1978-1987 Chevy Truck Type II steering wheel, accessed May 13, 2010 <http://67-72chevytrucks.com/vboard/showthread.php?t=335797>.  
 Photo of 2007 Chevy Silverado steering wheel, accessed May 13, 2010 <http://blogs.edmunds.com/roadtests/2008/03/2007-chevy-silverado-wear-and-tear-at-30k.html>.  
 Photo of Chevy Equinox steering wheel, accessed May 13, 2010 [http://saturn.gmcanada.com/images/vehicles/2010/chevrolet/equinox/chev\\_equi\\_int\\_ph\\_big\\_06.jpg](http://saturn.gmcanada.com/images/vehicles/2010/chevrolet/equinox/chev_equi_int_ph_big_06.jpg).  
 Photo of 2002 GMC Sierra steering wheel, accessed May 13, 2010 <http://www.qsl.net/kd4jux/sierra/index.html>.  
 Photo of Toyota Landcruiser Instrument cluster layouts, accessed May 13, 2010 <http://www.trailcandy.com/InsPanels.JPG>.  
 Photo of 1960 Chevy Impala dashboard, accessed May 14, 2010 [http://www.rodandcustommagazine.com/featuredvehicles/0911rc\\_1960\\_chevy\\_impala/photo\\_02.html](http://www.rodandcustommagazine.com/featuredvehicles/0911rc_1960_chevy_impala/photo_02.html).


\* cited by examiner



**FIG. 1**



**FIG. 2**



**FIG. 3**