



US00D797426S

(12) **United States Design Patent**
Wegener

(10) **Patent No.:** **US D797,426 S**

(45) **Date of Patent:** **** Sep. 19, 2017**

(54) **SOLE FOR FOOTWEAR**

13/28; A43B 13/30; A43B 13/32; A43B
13/34; A43B 13/36

See application file for complete search history.

(71) Applicant: **Bunzi Brands & Operations Pty
Limited**, Erskine Park, NSW (AU)

(56) **References Cited**

(72) Inventor: **Caleb Wegener**, Beecroft (AU)

U.S. PATENT DOCUMENTS

(73) Assignee: **BUNZL BRANDS & OPERATIONS
PTY LIMITED**, Erskine Park, NSW
(AU)

D321,977 S *	12/1991	Kilgore	D2/954
D326,179 S *	5/1992	Walker	D2/954
D356,671 S *	3/1995	Blanchini	D2/957
D378,241 S *	3/1997	Featherston	D2/954
D393,142 S *	4/1998	Brown	D2/900
D409,362 S *	5/1999	Turner	D2/951
D543,340 S *	5/2007	Favreau	A43B 13/141 D2/953
D561,438 S *	2/2008	Belley	D2/953
D569,086 S *	5/2008	Le	D2/953
D570,582 S *	6/2008	Roy	D2/953

(**) Term: **15 Years**

(21) Appl. No.: **29/570,333**

(Continued)

(22) Filed: **Jul. 7, 2016**

OTHER PUBLICATIONS

(30) **Foreign Application Priority Data**

Jan. 8, 2016 (AU) 201610094

Mack Terrapro Lace Up Safety Boots, MackBoots.com.au, [online],
[site visited Apr. 14, 2017]. <URL: <https://www.mackboots.com.au/terra-pro-boot#>>.*

(51) **LOC (10) Cl.** **02-04**

(Continued)

(52) **U.S. Cl.**

USPC **D2/960**; D2/947; D2/951; D2/953;
D2/957; D2/959

Primary Examiner — T. Chase Nelson

Assistant Examiner — Jonathan J Han

(58) **Field of Classification Search**

USPC D2/902, 906, 908, 916, 918, 925,
D2/946–962, 977; 36/1, 1.5, 3 B, 22 R,
36/24.5, 25 R, 28, 32 R, 34 R, 59 C,
36/67 A, 101–107, 114–116, 117.3, 117.4,
36/124–136

(74) *Attorney, Agent, or Firm* — McClure, Qualey &
Rodack, LLP



(57) **CLAIM**

The ornamental design for the sole for footwear, as shown
and described.

DESCRIPTION

FIG. 1 is a bottom view of my new sole for footwear, the top
view forming no part of the claimed invention;
FIG. 2 is a perspective view thereof;
FIG. 3 is a front view thereof;
FIG. 4 is a rear view thereof;
FIG. 5 is a left side view thereof; and,
FIG. 6 is a right side view thereof.

(Continued)



The broken lines in the figures form no part of the claimed design.

1 Claim, 6 Drawing Sheets

D744,728	S	*	12/2015	Remmele	D2/908
D746,562	S	*	1/2016	Babcock	D2/951
D756,093	S	*	5/2016	Mahoney	D2/951
D770,741	S	*	11/2016	Teteriatnikov	D2/951
2011/0131841	A1	*	6/2011	Foster	A43B 7/142 36/25 R

(56)

References Cited

U.S. PATENT DOCUMENTS

D586,544	S	*	2/2009	Fuerst	D2/951
D586,991	S	*	2/2009	Fuerst	D2/951
D591,943	S	*	5/2009	Recchi	D2/951
D593,290	S	*	6/2009	Chen	D2/951
D594,195	S	*	6/2009	Nakano	D2/951
D602,683	S	*	10/2009	Roundhouse	D2/951
D604,932	S	*	12/2009	Le	D2/951
7,707,748	B2	*	5/2010	Campbell	A43B 5/001 36/102
D697,296	S	*	1/2014	Loyley	D2/951
D710,078	S	*	8/2014	Joseph	D2/951
D711,083	S	*	8/2014	Tucker	D2/951
D712,122	S	*	9/2014	Tucker	D2/951
D713,135	S	*	9/2014	Tucker	D2/951
D724,297	S	*	3/2015	Oliver	D2/951
D724,830	S	*	3/2015	Joseph	D2/951
D736,509	S	*	8/2015	Bikowski	D2/951

OTHER PUBLICATIONS

Mack Terrapro Zip Safety Boots, MackBoots.com.au, [online], [site visited Apr. 14, 2017]. <URL: <https://www.mackboots.com.au/terrapro-zip-boot#>>.*

Adapt Range, YouTube.com, Mack Boots, Published on Mar. 1, 2017, [online], [site visited Apr. 14, 2017]. <URL: <https://www.youtube.com/watch?v=UuodwiiKPig>>.*

Royer 10-8400 Black FLX Rubber Sole Waterproof Leather Metal-Free Boot, SafetyCompany.com, [online], [site visited Apr. 14, 2017]. <URL: <https://www.safetycompany.com/foot-protection/industrial-safety-boots/royer-10-8400-black-flx-rubber-sole-waterproof-leather-metal-free-boot/>>.*

G.I. Tpye Sierra Sole Desert Tan Boot 3R-13W, RockysBig_Tall.com, [online], [site visited Apr. 14, 2017]. <URL: http://www.rockysbig-tall.com/store-products-5257-GI-Tpye-Sierra-Sole-Desert-Tan-Boot--3R-13W_42007595.html>.*

* cited by examiner




Fig 1



Fig 2




Fig 3




Fig 4




Fig 5




Fig 6