



US00D829320S

(12) **United States Design Patent** (10) **Patent No.:** **US D829,320 S**
Terai et al. (45) **Date of Patent:** **** Sep. 25, 2018**

(54) **AIR OUTLET OF AIR CONDITIONER FOR VEHICLE**

(71) Applicant: **TOYODA GOSEI CO., LTD.**,
Kiyosu-shi, Aichi-ken (JP)

(72) Inventors: **Nobuhiro Terai**, Kiyosu (JP); **Kenji Asano**, Nagoya (JP)

(73) Assignee: **TOYODA GOSEI CO., LTD.**,
Aichi-pref. (JP)

(**) Term: **15 Years**

(21) Appl. No.: **29/601,335**

(22) Filed: **Apr. 21, 2017**

(30) **Foreign Application Priority Data**

Dec. 27, 2016 (JP) 2016-028282
Dec. 27, 2016 (JP) 2016-028283

(51) **LOC (11) Cl.** **23-04**

(52) **U.S. Cl.**
USPC **D23/387**

(58) **Field of Classification Search**
USPC D23/386, 388, 392, 393, 397, 399, 400,
D23/406, 411, 412, 354; D8/321
(Continued)

(56) **References Cited**

U.S. PATENT DOCUMENTS

1,817,836 A * 8/1931 Petrelli F24F 13/15
454/325
2,154,731 A * 4/1939 Crowley B60S 1/54
239/284.1

(Continued)

OTHER PUBLICATIONS

Fiabilité Renault Problème de compresseur de climatisation, image post date Sep. 29, 2015, site visited May 25, 2018, (online),

<<http://www.largus.fr/actualite-automobile/fiabilite-renault-probleme-de-compresseur-de-climatisation-6597398.html>>.*

(Continued)

Primary Examiner — Kevin K Rudzinski

Assistant Examiner — Sean D Lough

(74) *Attorney, Agent, or Firm* — Posz Law Group, PLC



(57) **CLAIM**

The ornamental design for an air outlet of air conditioner for vehicle, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a first embodiment of an air outlet of air conditioner for vehicle showing our new design; FIG. 2 is a front elevation view thereof; FIG. 3 is a rear elevation view thereof; FIG. 4 is a left side elevation view thereof; FIG. 5 is a right side elevation view thereof; FIG. 6 is a top plan view thereof; FIG. 7 is a bottom plan view thereof; FIG. 8 is a perspective view thereof depicted in a secondary position of use; FIG. 9 is a front elevation view thereof depicted in the secondary position of use; FIG. 10 is a rear elevation view thereof depicted in the secondary position of use; FIG. 11 is a perspective view of a second embodiment of an air outlet of air conditioner for vehicle showing our new design; FIG. 12 is a front elevation view thereof; FIG. 13 is a rear elevation view thereof; FIG. 14 is a left side elevation view thereof; FIG. 15 is a right side elevation view thereof; FIG. 16 is a top plan view thereof; FIG. 17 is a bottom plan view thereof; FIG. 18 is a perspective view thereof depicted in a secondary position of use; FIG. 19 is a front elevation view thereof depicted in the secondary position of use; and, FIG. 20 is a rear elevation view thereof depicted in the secondary position of use.

(Continued)



The broken lines depict portions of the air outlet of air conditioner for vehicle that form no part of the claimed design.

1 Claim, 20 Drawing Sheets

(58) **Field of Classification Search**

CPC . A61L 9/125; B60H 1/345; B60S 1/54; E04B 1/92; E04B 7/02; F24F 13/06; F24F 1/0011; F24F 1/027; F24F 13/02; F24F 13/10; F24F 13/1426; F24F 13/15; F24F 13/20; E04D 13/10; F04D 25/14; F16L 3/003

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

2,293,065 A * 8/1942 Kiczales F24F 13/15
454/335
2,509,774 A * 5/1950 Leigh F24F 13/15
49/87.1
2,885,945 A * 5/1959 Reaney F24F 13/15
49/408
3,267,962 A * 8/1966 Josephson F24F 13/15
137/601.11
3,312,159 A * 4/1967 Shepherd A62C 2/16
454/369
3,313,226 A * 4/1967 Johnson F24F 13/15
454/319
3,358,577 A * 12/1967 Thomson F24F 13/06
454/320
3,403,615 A * 10/1968 Dayus F24F 13/06
454/309
3,436,016 A * 4/1969 Edwards F24F 11/76
236/49.5
3,683,786 A * 8/1972 Hedrick F24F 13/15
454/313
3,703,141 A * 11/1972 Pernoud B60H 1/345
239/519
3,783,768 A * 1/1974 Caming F24F 13/1406
454/335
3,894,481 A * 7/1975 Alley F16K 1/165
454/318
4,007,673 A * 2/1977 Zaloga F24F 13/075
415/125
D307,632 S * 5/1990 Schulz D23/392
D325,433 S * 4/1992 Siebert D23/382
5,188,561 A * 2/1993 Nissimoff F24F 11/00
454/256
D369,420 S * 4/1996 Haglund D25/38.1
D413,665 S * 9/1999 Hudson D23/370
D446,850 S * 8/2001 Arlotta D23/393
D449,680 S * 10/2001 Arlotta D23/393
D450,518 S * 11/2001 Frederick D6/630
6,389,832 B1 * 5/2002 Wu B01D 46/0005
62/201
D461,235 S * 8/2002 Arlotta D23/393
D466,605 S * 12/2002 Ziegler D23/393
D468,008 S * 12/2002 Fraser D23/390
D521,631 S * 5/2006 Habensus D23/388
D542,898 S * 5/2007 Juraschek D12/192
D608,432 S * 1/2010 Aruga D23/358
D639,416 S * 6/2011 Jones D23/393
D723,154 S * 2/2015 Cheng D23/412
D736,366 S * 8/2015 Picco D23/386

D754,830 S * 4/2016 Huang D23/351
D755,364 S * 5/2016 Vogtner D23/388
D758,257 S * 6/2016 Platto D12/163
D761,411 S * 7/2016 Schanzenbach D23/371
9,452,820 B1 * 9/2016 Wirth B64C 3/56
D783,136 S * 4/2017 Park D23/351
D785,158 S * 4/2017 Kern D23/388
D787,656 S * 5/2017 Yoo D23/351
D788,903 S * 6/2017 Kern D23/388
D801,512 S * 10/2017 Hall D23/388
D802,742 S * 11/2017 Sun D23/414
D816,825 S * 5/2018 Schanzenbach D23/371
D817,047 S * 5/2018 Barnes D6/703.5
2004/0152411 A1 * 8/2004 Gehring B60H 1/3414
454/153
2005/0042982 A1 * 2/2005 Okada B60H 1/3421
454/284
2005/0056037 A1 * 3/2005 Park F24F 1/0011
62/262
2007/0060040 A1 * 3/2007 Ogura B60H 1/3421
454/319
2008/0138194 A1 * 6/2008 Wei F04D 25/0613
415/121.2
2009/0149124 A1 * 6/2009 Stevenson B60H 1/00671
454/358
2009/0215378 A1 * 8/2009 Terai B60H 1/3428
454/152
2009/0298412 A1 * 12/2009 Gehring B60H 1/345
454/153
2011/0237176 A1 * 9/2011 Shibata B60H 1/3428
454/330
2014/0080399 A1 * 3/2014 Takai B60H 1/3421
454/155
2014/0120826 A1 * 5/2014 Takai F24F 13/075
454/318
2014/0148090 A1 * 5/2014 Shen G06F 1/20
454/358
2015/0065031 A1 * 3/2015 Shibata B60H 1/3421
454/322
2015/0253033 A1 * 9/2015 Zanqueta F24F 13/20
312/236
2015/0328959 A1 * 11/2015 Suzuki B60H 1/3421
454/155
2015/0360536 A1 * 12/2015 Terai B60H 1/00678
454/333
2016/0009163 A1 * 1/2016 Terai B60H 1/3421
454/155
2016/0216000 A1 * 7/2016 Monahan F24F 13/1413
2016/0227670 A1 * 8/2016 Liu H05K 7/20181
2017/0114545 A1 * 4/2017 Shopshire E04D 13/178
2017/0166035 A1 * 6/2017 Ahn B60H 1/345
2017/0176045 A1 * 6/2017 Terai F24F 13/1426
2017/0259649 A1 * 9/2017 Shibata B60H 1/3421
2017/0334266 A1 * 11/2017 Shibata B60H 1/345
2018/0023338 A1 * 1/2018 Werner E04F 10/08
160/167 R
2018/0087799 A1 * 3/2018 Pridemore F24F 11/74

OTHER PUBLICATIONS

Kixx Channel, image post date Aug. 16, 2016, site visited May 25, 2018, (online), <<https://kixxman.com/air-coditioner-maintenance-tips/>>.*
Tips Mudah Mengecek Kondisi Ac Mobil Supaya Awet, image post date Tue, Jan. 16, 2018, site visited May 25, 2018, (online), <<http://www.turbonesia.com/id/news/detail/tips-mudah-mengecek-kondisi-ac-mobil-supaya-awet/mobilmo>>.*

* cited by examiner

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20

