



US00D853097S

(12) **United States Design Patent** (10) **Patent No.:** **US D853,097 S**
Cass et al. (45) **Date of Patent:** **** Jul. 9, 2019**

(54) **FOOTWEAR SOLE**

(71) Applicant: **Wolverine Outdoors, Inc.**, Rockford,
MI (US)

(72) Inventors: **William Joseph Cass**, Belmont, MI
(US); **Clark Arvo Matis**, Durango, CO
(US)

(73) Assignee: **Wolverine Outdoors, Inc.**, Rockford,
MI (US)

(**) Term: **15 Years**

(21) Appl. No.: **29/621,331**

(22) Filed: **Oct. 6, 2017**

(51) **LOC (11) Cl.** **02-04**

(52) **U.S. Cl.**
USPC **D2/957**; D2/947; D2/951; D2/953;
D2/960

(58) **Field of Classification Search**

USPC D2/902, 906, 908, 916, 918, 925,
D2/946–962, 977; 36/1, 1.5, 3 B, 22 R,
36/24.5, 25 R, 28, 32 R, 34 R, 59 C,
36/67 A, 103, 101–107, 114–116, 117.3,
36/117.4, 124–136; D12/544
CPC A43B 13/00; A43B 13/02; A43B 13/023;
A43B 13/026; A43B 13/04; A43B 13/08;
A43B 13/10; A43B 13/12; A43B 13/14;
A43B 13/141; A43B 13/143; A43B
13/16; A43B 13/18; A43B 13/181; A43B
13/187; A43B 13/189; A43B 13/20; A43B
13/22; A43B 13/223; A43B 13/24; A43B
13/28; A43B 13/30; A43B 13/32; A43B
13/34; A43B 13/36

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D330,801 S * 11/1992 McDonald D2/954
D341,481 S * 11/1993 Peterson D2/959

D355,754 S * 2/1995 Brandon D2/951
D372,576 S * 8/1996 Mills et al.
D377,109 S * 1/1997 Manfredi D2/957
D389,294 S * 1/1998 Fogg D2/957
D390,691 S * 2/1998 Kayano D2/951
D399,341 S * 10/1998 Munns D2/951
D410,138 S * 5/1999 Turner D2/951

(Continued)

OTHER PUBLICATIONS

Flite Safety Toe Boot with Cleated Outsole, TingleyRubber.com,
[online], [site visited Oct. 5, 2018]. <URL: <http://www.tingleyrubber.com/p/flite-safety-toe-boot-with-cleated-outsole>> (Year: 2018).*

(Continued)

Primary Examiner — T Chase Nelson

Assistant Examiner — Jonathan J. Han

(74) *Attorney, Agent, or Firm* — Warner Norcross + Judd
LLP

(57) **CLAIM**

The ornamental design for footwear sole, as shown and
described.

DESCRIPTION

FIG. 1 is a perspective view of the footwear sole embodying
the new design;

FIG. 2 is a bottom view thereof;

FIG. 3 is a right side view thereof;


FIG. 4 is a left side view thereof;

FIG. 5 is a front view thereof; and,

FIG. 6 is a rear view thereof.

The broken lines shown in FIGS. 1-6 depict unclaimed
environmental structure with the exception of the broken
lines immediately around the perimeter of the claimed
footwear sole depicted in solid lines. These perimeter broken
lines depict a boundary that also forms no part of the claimed
design.

1 Claim, 5 Drawing Sheets



(56)

References Cited

U.S. PATENT DOCUMENTS

D420,497 S 2/2000 Panella
D431,710 S 10/2000 Panella
D431,894 S * 10/2000 Begg, II D2/957
D436,432 S 1/2001 Gams
D440,748 S 4/2001 Morgan
D471,347 S 3/2003 Haas et al.
D476,141 S 6/2003 Matis
D476,142 S 6/2003 Matis
D476,470 S 7/2003 Matis et al.
D495,476 S * 9/2004 Recchi D2/947
D498,042 S * 11/2004 Recchi D2/947
D500,401 S * 1/2005 Matis D2/953
D505,249 S 5/2005 Urie
D507,399 S 7/2005 White et al.
D509,346 S * 9/2005 Recchi D2/957
D518,280 S * 4/2006 Matis D2/951
D530,492 S * 10/2006 McClaskie D2/957
D546,534 S 7/2007 Belley et al.
D547,038 S 7/2007 Nakano
D550,437 S 9/2007 Belley et al.
D551,434 S 9/2007 Nakano
D554,840 S * 11/2007 McClaskie D2/953
D563,637 S 3/2008 Nakano
D564,192 S * 3/2008 Covatch D2/953
D564,740 S * 3/2008 Matis D2/956
D564,741 S * 3/2008 Covatch D2/953
D566,938 S * 4/2008 Matis D2/957
D567,492 S 4/2008 Belley et al.
D569,595 S * 5/2008 Le D2/957
D570,582 S 6/2008 Roy et al.

D574,583 S 8/2008 St-Louis et al.
D574,584 S * 8/2008 Earle D2/951
D594,195 S 6/2009 Nakano
D605,839 S * 12/2009 Horton D2/951
D635,753 S * 4/2011 Ng D2/951
D655,902 S * 3/2012 Debiase D2/951
D662,695 S * 7/2012 McVicker D2/902
D671,718 S * 12/2012 McVicker D2/908
D702,031 S 4/2014 Nakano
D702,032 S 4/2014 Nakano
D717,033 S * 11/2014 Law D2/951
D724,296 S * 3/2015 Law D2/951
D735,453 S * 8/2015 Monroy D2/951
D755,491 S 5/2016 Nakano
D756,095 S 5/2016 Nakano
D801,658 S * 11/2017 Huard D2/960
D811,705 S * 3/2018 Hughes D2/957

OTHER PUBLICATIONS

Rocky S2V Composite Toe Waterproof Work Boot, RockyBoots.com, [online], [site visited Oct. 5, 2018]. <URL: <https://www.rockyboots.com/sale/rocky-s2v-composite-toe-waterproof-work-boot/RKK0230.html>> (Year: 2018).*

Vibram App Trail, IowaBoots.com, [online], [site visited Oct. 5, 2018]. <URL: <https://www.iowaboats.com/about-Iowa/Iowa-sole-technology>> (Year: 2018).*

Dakota Women's CTCP Transitional Boots, RateMyTreads.com, [online], [site visited Oct. 5, 2018]. <URL: <http://www.ratemytreads.com/ratings/womens-work-footwear/dakota-ctcp-transitional-boots/>> (Year: 2018).*

* cited by examiner




Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6